





General information

| Make | LAND ROVER |
|---------------------|---------------------------------|
| Model | RANGE ROVER EVOQUE TD4 LANDMARK |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 124 mph |
| 0 - 100 km/h | 10.8 seconds |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 180 BHP |
|-------------------------|---------------------------|
| Max. torque | 430 Nm at 1.750 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 59.4 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-06-17 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-06-21 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| MOT #4 | | 2023-06-10 12:18 |
|-----------------------------------|---|------------------|
| MOT test number 1361840198 | | 136184019838 |
| Result VPa | | ✓ Passed |
| Next expi | ry date | 2024-06-21 |
| Advice | Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | ce Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii)) | |
| Advice | Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii)) | |
| Advice | Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| МОТ #3 | 2022-06-14 12:53 |
|-----------------|------------------|
| MOT test number | 954113372524 |
| Result | ✓ Passed |

| MOT #2 | 2022-06-14 09:12 |
|--|------------------|
| MOT test number | 385179080791 |
| Result | 🗙 Failed |
| Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |





| MOT #1 | | 2021-06-17 12:19 |
|----------|--|------------------|
| MOT test | number | 108749286812 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



Tax & MOT check

| √ Taxed | ✓ MOT |
|-----------------------------------|--------------------------|
| Tax due: 1 January 2025 | Expires: 21 June 2024 |
| Tax status | Valid until 1 January |
| Days left | 246 |
| MOT expiry date | 21 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | |
| Category | Low P |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Category | ampte |
| Туре | |

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





.....

More info \rightarrow

Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| More info > |
|-------------|
| |
| |
| |
| |

Number of plates

Current registration

Plata since



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-06-22 |
| Last registration | 2023-06-10 |
| Complete history | See info |



| Registration #1 | 2018-06-22 | 26 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-06-17 | 31.530 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.227 mi |
| Registration #6 | | 11.117 esi |



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 75% |
| Pedestrian | 41% |
| Safety systems | 86% |
| Overall rating | 75% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 2090 mm |
| Height | 1640 mm |
| Length | 4370 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1720 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 54 I |
| | 54 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |