




report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO
Colour	White
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	330 Nm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.8 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-11-11
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-17
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	9

MOT #6	2023-10-14 11:52
MOT test number	240215925145
Result	✓ Passed
Next expiry date	2024-10-17
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #5	2023-10-14 08:37
MOT test number	579389713804
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #4	2022-10-18 12:52
MOT test number	997120381796
Result	✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #3**

2022-10-17 16:24

MOT test number

562322343949

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail

Nearside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Front Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #2

2021-09-04 10:23

MOT test number

457028515700

Result**✓ Passed****Advice**

Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1

2020-09-19 10:11

MOT test number

133416479642

Result**✓ Passed**



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
17 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 NL67FKH
Plate since	2019-06-29
Current registration	 NL67FKH
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-30
Last registration	2023-10-14
Complete history	See info



Registration #1	2017-09-30	15 mi
Registration #2	2020-09-19	116.674 mi
Registration #3	2021-09-04	129.486 mi
Registration #4	2022-09-20	151.277 mi
Registration #5	2023-09-20	151.277 mi
Registration #6	2023-09-20	151.277 mi
Registration #7	2023-09-20	151.277 mi
Registration #8	2023-09-20	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	6198 mm
Kerb weight	1984 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C058600 L0B