



RA65LWH

report date: 2024-03-29

General information

Make	MINI
Model	CLUBMAN COOPER
Colour	White
Year of manufacture	2016
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	121 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	4
Total items failed	11

MOT #9	2024-02-06 12:28
MOT test number	886359733844
Result	✓ Passed
Next expiry date	2025-02-20
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2024-02-05 10:18
MOT test number	477905053624
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.0 (5.2.3 (e))

MOT #7	2023-01-30 09:46
MOT test number	772777567320
Result	✓ Passed

MOT #6	2022-01-31 09:24
MOT test number	637634163131
Result	✓ Passed

**MOT #5** 2021-02-08 12:47**MOT test number** 161829996748**Result** ✓ Passed**MOT #4** 2020-02-21 13:11**MOT test number** 850450854537**Result** ✓ Passed**Advice** Nearside Rear Inner Road wheel slightly distorted wheel buckled (5.2.2 (c) (i))**MOT #3** 2020-02-21 09:25**MOT test number** 323391077988**Result** ✗ Failed**Fail** Offside Rear All direction indicators not working (4.4.1 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords worn close to the legal limit and out of shape. (5.2.3 (d) (i))**Fail** Nearside Rear All direction indicators not working (4.4.1 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords worn close to the legal limit and out of shape. (5.2.3 (d) (i))**MOT #2** 2019-01-11 12:20**MOT test number** 441051784587**Result** ✓ Passed



MOT #1	2019-01-11 11:03
MOT test number	692750994838
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-01-14
Last registration	2024-02-06
Complete history	See info



Registration #1	2016-01-14	11 mi
Registration #2	2019-01-11	33.280 mi
Registration #3	2019-01-11	33.280 mi
Registration #4	2020-02-21	46.824 mi
Registration #5	2020-02-21	46.826 mi
Registration #6	2020-02-21	46.826 mi
Registration #7	2020-02-21	46.826 mi
Registration #8	2020-02-21	46.826 mi
Registration #9	2020-02-21	46.826 mi
Registration #10	2020-02-21	46.826 mi
Registration #11	2020-02-21	46.826 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	68%
Pedestrian	68%
Safety systems	67%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1375 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	F309H124