



report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | VAUXHALL |
| Model | ANTARA SE NAV CDTI S/S |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 117 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 161 BHP |
| Max. torque | 350 Nm at 2.000 rpm |
| Engine capacity | 2.231 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 44.1 mpg |
| CO2 emission | 170 g/km |
| CO2 label | H |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2024-03-20 |
| Pictures | 1 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|----------|------------|
| Date | 2022-03-29 |
| Pictures | 1 |



source: [cargurus.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-04-01 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 22 |
| Total items failed | 0 |

MOT #9 2023-03-29 11:10

MOT test number 731178422940

Result ✓ Passed

Next expiry date 2024-04-01

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material central long pipe (1.1.11 (c))
- Advice** Power steering component has slight seepage from a component Rack (2.1.5 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material central long pipe (1.1.11 (c))

MOT #8 2022-04-02 07:40

MOT test number 532275580685

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2022-03-29 15:16**MOT test number** 593677996830**Result** ✗ Failed

- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Rear Upper Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- MAJOR** Offside Rear Upper Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

MOT #6 2021-05-10 11:44**MOT test number** 228341669500**Result** ✓ Passed**MOT #5** 2020-05-14 14:30**MOT test number** 266069709065**Result** ✓ Passed



| | |
|------------------------|--|
| MOT #4 | 2020-05-13 12:02 |
| MOT test number | 523724852097 |
| Result | ✗ Failed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| MAJOR | Offside Brake pipe excessively corroded main at rear (1.1.11 (c)) |
| MAJOR | Nearside Brake pipe excessively corroded main at rear (1.1.11 (c)) |

| | |
|------------------------|------------------|
| MOT #3 | 2018-10-24 12:10 |
| MOT test number | 766283765259 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #2 | 2017-10-09 11:52 |
| MOT test number | 542515721219 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #1 | 2016-10-05 10:21 |
| MOT test number | 868527559951 |
| Result | ✓ Passed |



Tax & MOT check

X

Untaxed

Tax expired:
15 March 2024

X

MOT

Expired:
1 April 2024

| | |
|------------------|---------------------------------|
| Tax status | Expired at 15 March 2024 |
| Days left | 44 days too late |
| MOT expiry date | 1 April 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | SP13XOD |
| Plate since | 2019-03-28 |
| Current registration | SP13XOD |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2013-03-28 |
| Last registration | 2023-03-29 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-03-28 | 9 mi |
| Registration #2 | 2016-10-05 | 34.448 mi |
| Registration #3 | 2017-10-09 | 44.037 mi |
| Registration #4 | 2018-10-24 | 49.168 mi |
| Registration #5 | 2020-05-13 | 55.896 mi |
| Registration #6 | 2020-05-14 | 55.899 mi |
| Registration #7 | 2020-05-14 | 55.899 mi |
| Registration #8 | 2020-05-14 | 55.899 mi |
| Registration #9 | 2020-05-14 | 55.899 mi |
| Registration #10 | 2020-05-14 | 55.899 mi |
| Registration #11 | 2020-05-14 | 55.899 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 95% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2085 mm |
| Height | 1717 mm |
| Length | 4596 mm |
| Wheel base | 2707 mm |
| Kerb weight | 1896 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|-------------------|
| Fuel tank capacity | 65 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | Z22D1 291601K LNQ |