





## General information

Make N	IISSAN
Model PI	VIXO N-TEC
<b>Colour</b> Si	ilver
Year of manufacture 20	2010
Top speed 9	96 mph
<b>0 - 60 mph</b> 14	4.0 seconds
Gearbox 5	speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В







# Internet history


Entry 1

Date Pictures 2021-07-13

34

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-27
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #12	2023-06-19 08:55
MOT test number	988744596044
Result	✓ Passed
Next expiry date	2024-06-27

MOT #11	2022-05-30 09:37
MOT test number	213309144010
Result	✓ Passed

MOT #10	2021-06-28 08:32
MOT test number	905338881399
Result	✓ Passed

MOT #9	2021-01-07 13:04
MOT test	<b>number</b> 414371826291
Result	✓ Passed
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))





MOT #8		2019-07-09 11:08
MOT test	number	725015825339
Result		Passed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting ir	n excessive movement (5.3.4

MOT #7	2019-07-03 11:48
MOT test number	100639355002
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	)
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive m (a) (i))	ovement (5.3.4
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))	
<b>Fail</b> Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

MOT #6	2018-07-12 15:56
MOT test number	772505309019
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2017-02-20 12:59
MOT test number	774580308514
Result	✓ Passed
Advice Nearside Rear tyre scuffed on outer side wall	





MOT #4	2016-02-19 13:38
MOT test number	728066654109
Result	✓ Passed
MOT #3	2015-03-30 09:56
MOT test number	629029685045
Result	✓ Passed
MOT #2	2014-03-25 13:32
MOT test number	736854284072
Result	✓ Passed
MOT #1	2013-04-30 14:47
MOT test number	817860223126
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 27 June 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	27 June 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	 · · ·
Category	 AMPL
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-05-27
Last registration	2023-06-19
Complete history	See info



Registration #1	2010-05-27	7 mi
Registration #2	2013-04-30	32.482 mi
Registration #3	2014-03-25	40.186 mi
Registration #4	2015-03-30	48.879 mi
Registration #5	2016-02-19	56.385 mi
Registration #6	2017-02-20	64.715 mi
Registration #7	2018-07-12	73.816 mi
Registration #8		11.777 est
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #11 Registration #12		00.000 est
-		01.000 est 01.000 est 01.000 est





### Car features

50225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
60569	

# Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

## Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	112085