





report date: 2024-03-28

## General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Silver
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	M



CarCheck.co.uk page 1/14



## Internet history

### Entry 1

Date 2021-07-03

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-09-07
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	30
Total items failed	10

MOT #17	2023-09-07 09:32
MOT test number	273573436017
Result	✓ Passed
Next expiry date	2024-09-07
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2022-09-08 07:02
MOT test number	551844055502
Result	✓ Passed
MOT #15	2022-09-01 11:28
MOT test number	862402874425
Result	<b>X</b> Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #14		2020-11-30 16:54
MOT test	number	897518349905
Result		✓ Passed
Advice	Offside Front Head lamp has slight water condensation inside lamp	
Advice	Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #13** 2020-11-30 12:11

**MOT test number** 486687305674

**Result** X Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Position lamp with a multiple light source up to 1/2 not functioning Both rear outer not working (4.2.1 (a) (i))

Advice Offside Front Head lamp has slight water condensation inside lamp

Advice Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))

Minor Stop lamp(s) with a multiple light source up to 1/2 not functioning Both rear outer (4.3.1 (a) (i))

**MOT #12** 2019-05-13 16:57

**MOT test number** 901560554128

Result 

Passed

**MOT #11** 2019-05-13 09:59

**MOT test number** 205951488633

**Result** X Failed

**Advice** Nearside Front Nail in tyre

**Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

**Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Nearside Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #10** 2018-05-03 14:42

MOT test number 250423023407

**Result** ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #9 2017-06-02 14:33

**MOT test number** 925599270457

**Result** ✓ Passed

**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both front lower wishbone (2.4.G.2)

MOT #8 2017-06-01 09:02

MOT test number 875778033446

**Result** X Failed

**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both front lower wishbone (2.4.G.2)

**Fail** Tyre tread depth below requirements of 1.6mm both front (4.1.E.1)

**Advice** Nearside Rear Nail in tyre 2 X bedded on tyre not repairable

**Advice** Brake pad(s) wearing thin both front (3.5.1g)

**Fail** Offside Rear Tyre has ply or cords exposed outer wall damaged (4.1.D.1b)

Advice Strong advisory requires four wheel alignment

Advice Brake disc worn, pitted or scored, but not seriously weakened both front lipped and corroded

(3.5.1i)

MOT #7 2016-06-02 15:10

**MOT test number** 956444186708

**Result** 
✓ Passed

**Advice** Nearside Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front rear wishbone (2.4.G.2)

**Advice** Offside Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front rear wishbone (2.4.G.2)

MOT #6 2015-01-14 11:31

**MOT test number** 557904615017

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/14



report date: 2024-03-28

**MOT #5** 2014-01-28 14:42 249928024028 **MOT** test number ✓ Passed Result **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Off-side rear tyre has a tear in the inner side wall but not deep enough to reach the cords **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-01-28 14:42 166348224488 **MOT test number** Result × Failed Pass with rectification Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e) **Notice** Off-side rear tyre has a tear in the inner side wall but not deep enough to reach the cords **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Nearside Headlamp aim too low (1.8) Pass with rectification Nearside Stop lamp not working (1.2.1b) Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Offside Headlamp aim too high (1.8)

 MOT #3
 2013-01-18 15:03

 MOT test number
 609038313018

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #2	2012-05-10 15:34
MOT test number	528831732160
Result	<b>✓</b> Passed
MOT #1	2010-09-11 09:19
MOT test number	591654650263
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner History	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I	
********	
*************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIX
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-01
Last registration	2023-09-07
Complete history	See info



Registration #1	2007-09-01	22 mi
Registration #2	2010-09-11	33.471 mi
Registration #3	2012-05-10	57.563 mi
Registration #4	2013-01-18	63.517 mi
Registration #5	2014-01-28	74.049 mi
Registration #6	2015-01-14	80.846 mi
Registration #7	2016-06-02	93.281 mi
Registration #8	2017-06-01	103.259 mi
Registration #9	2017-06-02	103.262 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		91,700 esi
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

# Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14