





report date: 2024-03-28

## General information

Make	CITROEN
Model	DS3 E-HDI FLAIR ETG6
Colour	Red
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	91 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/12



HN640BU

report date: 2024-03-28

## Internet history

## Entry 1


Date 2022-04-27

Pictures 38

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## **MOT** history

MOT expiry date	2024-05-06
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	17
Total items failed	4

MOT #11	2023-04-27 10:49
MOT test number	359844924279
Result	✓ Passed
Next expiry date 2024-05-06	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated boot is loose on cv joint (6.1.7 (g) (i))  Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2022-05-07 10:07
MOT test number	484097823766
Result	<b>✓</b> Passed

MOT #9	2022-05-03 14:00
MOT test number	540935603935
Result	<b>X</b> Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))  Advice Rear exhaust bracket broken	

CarCheck.co.uk page 3/12



HN640BU

report date: 2024-03-28

MOT test number

Result

Advice Front Outer Tyre slightly damaged Both sidewalls (5.2.3 (d) (ii))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT test number

Result

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Front Outer Tyre slightly damaged Both sidewalls (5.2.3 (d) (ii))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #6** 2021-09-30 16:29 346964261496 **MOT** test number Result × Failed Advice Rear Exhaust mounting defective Backbox mount corroded off but has 2nd support (6.1.2 (a)) Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Worn/pitted (1.1.14 (a) (ii)) Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Worn/pitted (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

460096191820

Result

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #4

Result

Advice Rear Exhaust mounting defective (6.1.2 (a))

Fail Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #3

MOT test number

107821223826

Result

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

 MOT #2
 2018-09-29 11:08

 MOT test number
 371953269232

 Result
 ✓ Passed

 MOT #1
 2018-01-10 11:19

 MOT test number
 284696263640

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check



Tax status	valid until 1 May
Days left	3
MOT expiry date	6 May 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

_	
Owner	hictory
	1113601 1

e which misterly	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	
THE PARTY OF THE P	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK ZAS
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-01-07
Last registration	2023-04-27
Complete history	See info



Registration #1	2015-01-07	12 mi
Registration #2	2018-01-10	22.397 mi
Registration #3	2018-09-29	25.574 mi
Registration #4	2019-09-24	35.937 mi
Registration #5	2020-10-02	42.043 mi
Registration #6	2020-10-03	42.044 mi
Registration #7	2021-09-30	47.833 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.777 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1946 mm
Height	1540 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1055 kg
Max. allowed weight	1605 kg

## Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBFN0073270

CarCheck.co.uk page 12/12