




report date: 2024-03-29

General information

Make	VOLVO
Model	C70 T5 SE
Colour	Black
Year of manufacture	2006
Top speed	146 mph
0 - 60 mph	7.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	28.8 mpg
CO2 emission	234 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-05-26
Pictures	45
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-25
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	43
Total items failed	6

MOT #19 2023-04-26 13:37

MOT test number 706753753087

Result ✓ Passed

Next expiry date 2024-04-25

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #18 2022-03-19 11:48

MOT test number 615089600232

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2022-03-07 13:50

MOT test number

412431918070

Result**✗ Failed**

- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Rear Tyre slightly damaged/cracking or perishing both n/s and o/s (5.2.3 (d) (ii))
- MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- DANGEROUS** Rear Tyre has ply or cords exposed both n/s and o/s 235/40/18 (5.2.3 (d) (ii))
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both n/s and o/s (4.7.1 (b) (ii))
- DANGEROUS** Rear Tyre tread depth below requirements of 1.6mm both n/s and o/s (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16

2021-02-24 13:14

MOT test number

787805273485

Result**✓ Passed**

- Advice** Rear Tyre slightly damaged/cracking or perishing both n/s and o/s (5.2.3 (d) (ii))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both n/s and o/s (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2020-03-06 17:14

MOT test number

135145621147

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing both n/s and o/s (5.2.3 (d) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both n/s and o/s on limit (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14**

2019-01-10 09:31

MOT test number

991264611832

Result

✓ Passed

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2018-01-13 10:58

MOT test number

586882582882

Result

✓ Passed

Advice Nearside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement back inner (2.4.G.2)**Advice** Offside Rear shock absorber reduced damping effect**MOT #12**

2016-12-29 16:30

MOT test number

309202782571

Result

✓ Passed

**MOT #11** 2016-12-28 15:14**MOT test number** 788942564957**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #10** 2016-01-06 11:14**MOT test number** 782635152614**Result** ✓ Passed**Advice** Front Inner Tyre worn close to the legal limit both (4.1.E.1)**MOT #9** 2014-10-11 09:36**MOT test number** 937294184245**Result** ✓ Passed**MOT #8** 2013-10-04 11:45**MOT test number** 389987573489**Result** ✓ Passed**Notice** Nsf and osf tyres showing wear on inner treads**Notice** Both rear indicator bulbs showing discolour**Notice** Engine oil on min

**MOT #7** 2013-10-04 09:07**MOT test number** 658677273249**Result** ✗ Failed**Notice** Nsf and osf tyres showing wear on inner treads**Notice** Both rear indicator bulbs showing discolour**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Engine oil on min**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2012-09-19 08:51**MOT test number** 317383862225**Result** ✓ Passed**MOT #5** 2011-09-09 15:57**MOT test number** 345232951206**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-09-09 14:28**MOT test number** 815992351210**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2010-08-16 14:13
---------------	------------------

MOT test number	363278820243
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	N/S AND O/S FRONT TYRER SIDEWALLS HAVE SLIGHT CUT IN THEM.
---------------	--

MOT #2	2010-08-13 10:23
---------------	------------------

MOT test number	350925920245
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Steering rack gaiter split (2.2.D.2d)
-------------	--

Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
-------------	---

Notice	N/S AND O/S FRONT TYRER SIDEWALLS HAVE SLIGHT CUT IN THEM.
---------------	--

MOT #1	2009-07-23 15:23
---------------	------------------

MOT test number	901964809211
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-26
Last registration	2023-04-26
Complete history	See info



Registration #1	2006-07-26	10 mi
Registration #2	2009-07-23	17.820 mi
Registration #3	2010-08-13	25.201 mi
Registration #4	2010-08-16	25.201 mi
Registration #5	2011-09-09	32.986 mi
Registration #6	2011-09-09	32.988 mi
Registration #7	2012-09-19	41.275 mi
Registration #8	2013-10-04	52.083 mi
Registration #9	2013-10-04	52.083 mi
Registration #10	2014-10-11	62.146 mi
Registration #11	2016-01-06	70.432 mi
Registration #12	2016-01-06	70.432 mi
Registration #13	2016-01-06	70.432 mi
Registration #14	2016-01-06	70.432 mi
Registration #15	2016-01-06	70.432 mi
Registration #16	2016-01-06	70.432 mi
Registration #17	2016-01-06	70.432 mi
Registration #18	2016-01-06	70.432 mi
Registration #19	2016-01-06	70.432 mi
Registration #20	2016-01-06	70.432 mi
Registration #21	2016-01-06	70.432 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1651 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	3942349