





report date: 2024-03-28

#### General information

| Make                | RENAULT           |
|---------------------|-------------------|
| Model               | ZOE DYNAMIQUE ZEN |
| Colour              | Grey              |
| Year of manufacture | 2013              |
| Top speed           | 84 mph            |
| 0 - 60 mph          | 13.5 seconds      |
| Gearbox             | 1 speed automatic |

### Engine & fuel consumption

| Power       | 87 BHP              |
|-------------|---------------------|
| Max. torque | 220 Nm at 2.500 rpm |
| Fuel type   | Electricity         |



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date 2021-07-02

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



LV63XVX

report date: 2024-03-28

#### **MOT** history

| MOT expiry date    | 2024-10-31 |
|--------------------|------------|
| MOT pass rate      | 78 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 2          |
| Total advice items | 25         |
| Total items failed | 6          |

| MOT #9           | 2023-10-03 10:11 |
|------------------|------------------|
| MOT test number  | 743436639030     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2024-10-31       |

| MOT #8          | 2022-10-04 08:08 |
|-----------------|------------------|
| MOT test number | 395885856203     |
| Result          | ✓ Passed         |
|                 |                  |

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 185/65 R15 88T Bridgestone Turanza (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm only,worn on inside edge 185/65 R15 88T Bridgestone Turanza (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 185/65 R15 88T Bridgestone Turanza (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm only,worn on inside edge 185/65 R15 88T Bridgestone Turanza (5.2.3 (e))

CarCheck.co.uk page 3/12



Passed

MOT #7 2021-10-08 09:33

**MOT test number** 265974197411

Advice Offside Front Tyre worn close to legal limit/worn on edge 4mm only, worn on inside edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge 4mm only, slightly cracked/perished

(5.2.3 (e))

**Advice** 

(e)

Result

Handbrake has long travel

Advice Nearside Front Tyre worn close to legal limit/worn on edge 4mm only, worn on inside edge (5.2.3

Advice Nearside Rear Tyre starting to wear on both edges

MOT #6 2020-10-29 15:31

**MOT test number** 455712908803

**Result** 
✓ Passed

Advice Vehicles internal headlight adjuster altered to recheck lights

MOT #5 2019-10-30 12:43

**MOT test number** 210444137338

**Result** ✓ Passed

**Advice** Nearside Rear Nail in tyre

Advice Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-10-24 09:42

**MOT test number** 590125322841

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



LV63XVX

report date: 2024-03-28

**MOT #3** 2018-10-24 09:42 **MOT** test number 748645879286 Result × Failed **Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Pass with rectification Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #2

MOT test number

222954749723

Result

Advice

Nearside Rear slight damage to side wall

Advice

Front brake disc modified but not seriously weakened nearside and offside (3.5.1n)

Advice


Nearside Rear wheel bearing has slight play very slight (2.6.2)

**MOT #1** 2017-10-30 12:12 **MOT** test number 288179338665 Result × Failed Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Front Tyre has ply or cords exposed cut in side wall (4.1.D.1b) **Advice** Front brake disc modified but not seriously weakened nearside and offside (3.5.1n) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Front registration plate insecure (6.3.1b) Advice Nearside Rear slight damage to side wall Advice Nearside Rear wheel bearing has slight play very slight (2.6.2)

CarCheck.co.uk page 5/12



#### Tax & MOT check



Days left94MOT expiry date31 October 2024

Full MOT history See MOT history


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. |           | AULT |
|--|-----------|------|
|  |           |      |
|  |           |      |
|  |           |      |
|  |           |      |
| *******  |           |      |
|  |           |      |
| ***************************************  |           |      |
|  |           |      |
|  | More info | >    |
| Plate changes  |           |      |
| See in this check if this RENAULT had different number plates.   |           |      |
| Number of plates   |           | ,    |
| Current registration   | UK        |      |
| Plate since  |           |      |
| Current registration   | UK UK     |      |
| Plate since  |           |      |
|  | More info | >    |
|  |           |      |

CarCheck.co.uk page 9/12



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 11         |
| First mileage registration | 2013-12-30 |
| Last registration          | 2023-10-03 |
| Complete history           | See info   |



| Registration #1  | 2013-12-30 | 8 mi      |
|------------------|------------|-----------|
| Registration #2  | 2017-10-30 | 14.477 mi |
| Registration #3  | 2017-11-01 | 14.524 mi |
| Registration #4  | 2018-10-24 | 25.446 mi |
| Registration #5  | 2018-10-24 | 25.446 mi |
| Registration #6  | 2019-10-30 | 34.943 mi |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 19.777 es |

More info >

CarCheck.co.uk page 11/12



### Car features

| S0225 | Air conditionin |
|-------|-----------------|
| 50295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 60567 |                 |
| 50569 |                 |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 89%             |
| Children       | 80%             |
| Pedestrian     | 66%             |
| Safety systems | 85%             |
| Overall rating | 82%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 1730 mm |
|---------------------|---------|
| Height              | 1562 mm |
| Length              | 4084 mm |
| Wheel base          | 2588 mm |
| Kerb weight         | 1468 kg |
| Max. allowed weight | 1943 kg |

# Additional information

| Fuel delivery                     | Not Applicable |
|-----------------------------------|----------------|
| Number of doors                   | 5              |
| Number of seats                   | 5              |
| Number of axles<br>Carcheck.co.uk | 2 page 12/1    |