



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI ACTIVE BLUE DRIVE
Colour	White
Year of manufacture	2014
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	80.7 mpg
Consumption combined	76.3 mpg
CO2 emission	97 g/km
CO2 label	A





MOT history

MOT expiry date	2024-10-27
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	9

MOT #11	2023-10-24 13:17
MOT test number	348302350457
Result	✓ Passed
Next expiry date	2024-10-27
Advice	Rear Brake pad(s) wearing thin BOTH REAR (1.1.13 (a) (ii))

MOT #10	2022-10-28 11:51
MOT test number	647569179884
Result	✓ Passed

MOT #9	2022-10-27 13:03
MOT test number	122281300287
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #8	2021-10-21 16:14
MOT test number	114210940796
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt

**MOT #7**

2021-10-20 10:46

MOT test number

474337069111

Result**✗ Failed****Advice**

Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Side repeater slightly discoloured (4.4.3 (a))

Fail

Nearside Side repeater incorrect colour (4.4.3 (a))

FailNearside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt Insecure.
(2.1.3 (g) (ii))**Minor**

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #6

2020-10-16 09:27

MOT test number

665573315146

Result**✓ Passed****Advice**

Both rear tyres perished

Advice

Offside Rear door check strap missing

Advice

Nearside Rear tyre worn on outer edge

Advice

Nearside Rear fog lamp inop

**MOT #5** 2020-10-15 13:59**MOT test number** 308797904993**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp likely to become detached (4.7.1 (c) (ii))**Advice** Offside Rear door check strap missing**Advice** Nearside Rear tyre worn on outer edge**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Rear reflector missing (4.8.2 (a) (ii))**Advice** Nearside Rear fog lamp inop**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Both rear tyres perished**MOT #4** 2019-10-15 08:43**MOT test number** 724768380919**Result** ✓ Passed**Advice** Nearside Rear tyre worn to 3mm tread**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Tyre pressure monitoring system light indicating low tyre pressure at time of test**MOT #3** 2018-10-10 10:49**MOT test number** 906244381009**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #2	2017-10-23 14:07
MOT test number	415965710464
Result	✓ Passed

MOT #1	2017-10-23 10:54
MOT test number	641098001089
Result	✗ Failed
Fail	Nearside Front Inner Tyre tread depth below requirements of 1.6mm down to 1mm in places (4.1.E.1)
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm down to 1mm in places (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
27 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EK64APZ
Plate since	2019-09-28
Current registration	EK64APZ
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-10-24
Last registration	2023-10-24
Complete history	See info



Registration #1	2014-10-24	25 mi
Registration #2	2017-10-23	25.493 mi
Registration #3	2017-10-23	25.493 mi
Registration #4	2018-10-10	30.330 mi
Registration #5	2019-10-15	37.780 mi
Registration #6	2020-10-15	45.162 mi
Registration #7	2023-10-24	55.377 mi
Registration #8	2023-10-24	55.377 mi
Registration #9	2023-10-24	55.377 mi
Registration #10	2023-10-24	55.377 mi
Registration #11	2023-10-24	55.377 mi
Registration #12	2023-10-24	55.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1360 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4FBEZ568579