



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PRIUS VVT-I T3
Colour	Grey
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	72.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	72.4 mpg
CO2 emission	89 g/km
CO2 label	A





## MOT history

MOT expiry date	2024-11-29
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	24
Total items failed	13

MOT #25	2023-11-30 18:09
MOT test number	761723851811
Result	✓ Passed
Next expiry date	2024-11-29
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #24	2023-11-30 18:09
MOT test number	131319820938
Result	✗ Failed
Pass with rectification	Offside Front Side repeater not working (4.4.1 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #23	2023-11-13 18:37
MOT test number	260335202489
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22** 2023-01-05 13:35**MOT test number** 399662556708**Result** ✓ Passed**MOT #21** 2022-05-09 11:11**MOT test number** 537289360263**Result** ✓ Passed**MOT #20** 2022-05-09 11:11**MOT test number** 260082361109**Result** ✗ Failed**Pass with rectification** Front Position lamp not working (4.2.1 (a) (ii))**MOT #19** 2021-11-10 18:18**MOT test number** 978730236456**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2021-05-15 17:23**MOT test number** 792950774059**Result** ✓ Passed**MOT #17** 2020-11-09 14:36**MOT test number** 548874190509**Result** ✓ Passed

**MOT #16** 2020-11-09 14:09**MOT test number** 831816078923**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #15** 2020-06-13 15:51**MOT test number** 591877867691**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #14** 2020-06-13 15:51**MOT test number** 980926089960**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #13** 2019-11-12 15:54**MOT test number** 875747918901**Result** ✓ Passed**MOT #12** 2019-06-27 11:41**MOT test number** 137445472430**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2019-06-27 09:47**MOT test number** 543860191524**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2018-12-27 10:09**MOT test number** 976730606547**Result** ✓ Passed**MOT #9** 2018-12-03 14:01**MOT test number** 905517562604**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-12-03 14:01**MOT test number** 518979416521**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Front Headlamp aim so that beam "kick up" is not visible on the screen both side (4.1.2 (a))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Front Position lamp not working both side (4.2.1 (a))**MOT #7** 2018-06-02 10:57**MOT test number** 667113442598**Result** ✓ Passed**MOT #6** 2017-12-04 12:00**MOT test number** 791607219682**Result** ✓ Passed**MOT #5** 2017-06-06 15:04**MOT test number** 343589888433**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-06-06 15:04**MOT test number** 721301258009**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp not working both (1.1.C.1d)**Pass with rectification** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2016-12-07 15:03
MOT test number	833912012801
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Tyre worn close to the legal limit both sides (4.1.E.1)

MOT #2	2016-06-10 15:58
MOT test number	287013626999
Result	✓ Passed

MOT #1	2015-12-14 11:39
MOT test number	884537649316
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	29 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	59
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2014-12-18
Last registration	2023-11-30
Complete history	<a href="#">See info</a>



Registration #1	2014-12-18	27 mi
Registration #2	2015-12-14	28.524 mi
Registration #3	2016-06-10	41.365 mi
Registration #4	2016-12-07	53.844 mi
Registration #5	2017-06-06	70.753 mi
Registration #6	2017-06-06	70.753 mi
Registration #7	2017-12-04	84.479 mi
Registration #8	2018-06-02	103.365 mi
Registration #9	2018-12-03	118.650 mi
Registration #10	2018-12-03	118.650 mi
Registration #11	2018-12-27	119.561 mi
Registration #12	2019-06-27	141.189 mi
Registration #13	2019-06-27	141.193 mi
Registration #14	2019-06-27	141.193 mi
Registration #15	2019-06-27	141.193 mi
Registration #16	2019-06-27	141.193 mi
Registration #17	2019-06-27	141.193 mi
Registration #18	2019-06-27	141.193 mi
Registration #19	2019-06-27	141.193 mi
Registration #20	2019-06-27	141.193 mi
Registration #21	2019-06-27	141.193 mi
Registration #22	2019-06-27	141.193 mi
Registration #23	2019-06-27	141.193 mi
Registration #24	2019-06-27	141.193 mi
Registration #25	2019-06-27	141.193 mi
Registration #26	2019-06-27	141.193 mi

**More info** >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1425 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

2ZRU870525