



DPI40NU

report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 33 B/B C/C MULTIJET
Colour	White
Year of manufacture	2014
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	2.287 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	39.8 mpg
CO2 emission	186 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-02-09
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-09-21
<b>MOT pass rate</b>	88 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	16
<b>Total items failed</b>	3

<b>MOT #8</b>	2023-09-22 16:07
<b>MOT test number</b>	600763017161
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-21
<b>Advice</b>	Some corrosion on exhaust
<b>Advice</b>	Zero emissions

<b>MOT #7</b>	2022-03-23 09:55
<b>MOT test number</b>	617952478074
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2021-07-09 10:46
<b>MOT test number</b>	139930563968
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Exhaust rear box corroded
<b>Advice</b>	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Exhaust mounting defective rear box rubbers (6.1.2 (a))

**MOT #5** 2021-07-09 09:22**MOT test number** 981860822408**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust rear box corroded**Advice** Exhaust mounting defective rear box rubbers (6.1.2 (a))**MOT #4** 2020-07-20 12:25**MOT test number** 164647992462**Result** ✓ Passed**Advice** Rear exhaust box outer skin corroded**MOT #3** 2019-07-18 09:57**MOT test number** 683214243414**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #2	2018-07-10 16:51
MOT test number	481432017899
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MOT #1	2017-07-20 11:10
MOT test number	902478847263
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
21 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-07-22
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	2014-07-22	25 mi
Registration #2	2017-07-20	23.234 mi
Registration #3	2018-07-10	27.755 mi
Registration #4	2019-07-18	32.193 mi
Registration #5	2020-07-20	35.755 mi
Registration #6	2020-09-22	35.755 mi
Registration #7	2020-09-22	35.755 mi
Registration #8	2020-09-22	35.755 mi
Registration #9	2020-09-22	35.755 mi
Registration #10	2020-09-22	35.755 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	2254 mm
Length	5358 mm
Kerb weight	1637 kg
Max. allowed weight	3300 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	1915353