



report date: 2024-03-28

General information

Make	KIA
Model	VENGA 1
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 4.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	45.6 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-08
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	21
Total items failed	7

MOT #16	2024-01-12 08:52
MOT test number	627078080400
Result	✓ Passed
Next expiry date	2025-01-11

MOT #15	2023-11-10 11:13
MOT test number	556112053725

Result	✗ Failed
--------	----------

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge On 3mm (5.2.3 (e))

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge On 3mm (5.2.3 (e))

Fail Rear fog lamp not working Does Not Illuminate On Dashboard (4.5.1 (a) (ii))

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #14**

2022-11-08 14:21

MOT test number

981457904177

Result

✓ Passed

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13

2021-10-15 14:28

MOT test number

438743385223

Result

✓ Passed

Minor Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both front dust covers perished (2.1.3 (g) (i))

Minor Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #12

2021-10-15 09:49

MOT test number

578325935793

Result

✗ Failed

Minor Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both front dust covers perished (2.1.3 (g) (i))

Advice Nearside Rear Nail in tyre

Minor Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Nearside Front Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #11

2020-10-15 09:17

MOT test number

897913223637

Result

✓ Passed

**MOT #10** 2020-10-15 09:17**MOT test number** 776750461810**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))**MOT #9** 2019-04-18 16:01**MOT test number** 132938890827**Result** ✓ Passed**MOT #8** 2019-03-23 10:44**MOT test number** 401126890186**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-03-22 11:54**MOT test number** 307753922084**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Central Rear Seat belt retracting mechanism defective (7.1.2 (e))



MOT #6	2018-03-23 14:03
MOT test number	765654970467
Result	✓ Passed
MOT #5	2017-03-23 16:40
MOT test number	407906640264
Result	✓ Passed
MOT #4	2016-03-16 14:44
MOT test number	995325579899
Result	✓ Passed
MOT #3	2015-03-18 16:32
MOT test number	436267375067
Result	✓ Passed
MOT #2	2015-03-18 15:47
MOT test number	107037475046
Result	✗ Failed
<div><div>Fail</div> Stop lamp not working (1.2.1b)</div> <div><div>Fail</div> Windscreen wiper does not clear the windscreen effectively (8.2.2)</div>	
MOT #1	2014-03-18 15:50
MOT test number	486767274056
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-25
Last registration	2024-01-12
Complete history	See info



Registration #1	2011-03-25	28 mi
Registration #2	2014-03-18	9.456 mi
Registration #3	2015-03-18	12.824 mi
Registration #4	2015-03-18	12.825 mi
Registration #5	2016-03-16	14.836 mi
Registration #6	2017-03-23	17.830 mi
Registration #7	2018-03-23	20.094 mi
Registration #8	2019-03-22	24.086 mi
Registration #9	2019-03-23	24.088 mi
Registration #10	2020-03-23	25.277 mi
Registration #11	2020-03-23	25.277 mi
Registration #12	2020-03-23	25.277 mi
Registration #13	2020-03-23	25.277 mi
Registration #14	2020-03-23	25.277 mi
Registration #15	2020-03-23	25.277 mi
Registration #16	2020-03-23	25.277 mi
Registration #17	2020-03-23	25.277 mi
Registration #18	2020-03-23	25.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FAAZ290587