



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-29
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-28
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	51
Total items failed	19

MOT #23	2023-10-11 13:27
MOT test number	105551704262
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #22**

2022-09-29 16:01

**MOT test number**

794691276209

**Result**

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #21**

2022-09-29 07:51

**MOT test number**

956314550572

**Result****✗ Failed**

- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #20**

2021-10-02 16:37

**MOT test number**

120615376131

**Result****✓ Passed****MOT #19**

2021-09-29 15:30

**MOT test number**

110592946562

**Result****✗ Failed**

- Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #18** 2020-09-23 12:06**MOT test number** 717562049229**Result** ✓ Passed**MOT #17** 2020-09-22 14:19**MOT test number** 593241576464**Result** ✗ Failed**Fail** Offside Rear Headlamp lens seriously defective (4.1.1 (b) (ii))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #16** 2019-09-25 14:48**MOT test number** 182688272891**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15** 2019-09-24 10:30**MOT test number** 216343923021**Result** ✗ Failed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Rear Direction indicator incorrect colour both (4.4.3 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14**

2018-09-26 14:55

**MOT test number**

659905720016

**Result**

✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #13**

2018-09-24 11:25

**MOT test number**

256144850045

**Result**

✗ Failed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Shock absorbers damaged to the extent that it does not function (5.3.2 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12**

2017-09-20 13:29

**MOT test number**

555105422421

**Result**

✓ Passed

- Advice** Offside Front Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #11** 2016-09-23 13:04**MOT test number** 859548461530**Result** ✓ Passed**MOT #10** 2016-09-22 13:43**MOT test number** 230809170631**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Abs light**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9** 2015-09-25 14:06**MOT test number** 515475656871**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-09-24 14:44**MOT test number** 616167264203**Result** ✓ Passed**MOT #7** 2013-09-24 14:15**MOT test number** 415147963255**Result** ✓ Passed



**MOT #6** 2013-09-19 14:56**MOT test number** 368742263254**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #5** 2012-09-25 12:45**MOT test number** 509159762240**Result** ✓ Passed**MOT #4** 2012-09-21 11:37**MOT test number** 888835362258**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-09-21 14:41**MOT test number** 797994661299**Result** ✓ Passed**MOT #2** 2011-09-19 09:59**MOT test number** 918922761207**Result** ✗ Failed**Fail** Offside Rear coil spring incomplete (2.4.C.1a)



MOT #1	2010-09-20 11:37
MOT test number	712623660225
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
10 October 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	10 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>KG57AUT</b>
Plate since	2024-03-29
Current registration	 <b>KG57AUT</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-26
Last registration	2023-10-11
Complete history	<a href="#">See info</a>



Registration #1	2007-09-26	22 mi
Registration #2	2010-09-20	34.758 mi
Registration #3	2011-09-19	41.034 mi
Registration #4	2011-09-21	41.049 mi
Registration #5	2012-09-21	47.283 mi
Registration #6	2012-09-25	47.363 mi
Registration #7	2013-09-19	51.786 mi
Registration #8	2013-09-24	51.848 mi
Registration #9	2014-09-24	56.957 mi
Registration #10	2015-09-25	63.364 mi
Registration #11	2016-09-22	70.581 mi
Registration #12	2016-09-23	70.625 mi
Registration #13	2017-09-20	76.388 mi
Registration #14	2018-09-20	82.151 mi
Registration #15	2019-09-20	87.914 mi
Registration #16	2020-09-20	93.677 mi
Registration #17	2021-09-20	99.440 mi
Registration #18	2022-09-20	105.203 mi
Registration #19	2023-09-20	110.966 mi
Registration #20	2024-09-20	116.729 mi
Registration #21	2025-09-20	122.492 mi
Registration #22	2026-09-20	128.255 mi
Registration #23	2027-09-20	134.018 mi
Registration #24	2028-09-20	139.781 mi
Registration #25	2029-09-20	145.544 mi
Registration #26	2030-09-20	151.307 mi



**More info** >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118