



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI
Colour	White
Year of manufacture	2012
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-09-04
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #12	2023-09-07 13:42
MOT test number	976851325956
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2023-08-30 12:40**MOT test number** 886687721711**Result** ✗ Failed

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2022-09-13 08:15**MOT test number** 144475445527**Result** ✓ Passed**MOT #9** 2022-09-02 15:59**MOT test number** 719454960207**Result** ✗ Failed

- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #8 2021-08-13 11:40**MOT test number** 801661215567**Result** ✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #7** 2021-08-13 10:53**MOT test number** 267622386758**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2020-08-17 10:36**MOT test number** 644054345465**Result** ✓ Passed**MOT #5** 2019-09-18 13:18**MOT test number** 845642925777**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-09-18 08:59**MOT test number** 688501034971**Result** ✓ Passed



MOT #3	2017-09-19 08:24
MOT test number	474963089978
Result	✓ Passed
Advice	Under trays fitted
Advice	Bonnet covers fitted

MOT #2	2016-09-23 08:46
MOT test number	991666676725
Result	✓ Passed
Advice	Nearside Front Front wheel bearing has slight play (2.5.A.3c)
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1	2015-09-24 15:10
MOT test number	613051836025
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YR62PVX
Plate since	2019-09-29
Current registration	YR62PVX
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-28
Last registration	2023-09-07
Complete history	See info



Registration #1	2012-09-28	22 mi
Registration #2	2015-09-24	6.184 mi
Registration #3	2016-09-23	12.545 mi
Registration #4	2017-09-19	21.179 mi
Registration #5	2018-09-18	29.011 mi
Registration #6	2019-09-18	39.611 mi
Registration #7	2020-08-17	50.466 mi
Registration #8	2021-08-17	50.466 mi
Registration #9	2022-08-17	50.466 mi
Registration #10	2023-08-17	50.466 mi
Registration #11	2024-08-17	50.466 mi
Registration #12	2025-08-17	50.466 mi
Registration #13	2026-08-17	50.466 mi
Registration #14	2027-08-17	50.466 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

Number of axles	2
Engine number	G4FDCU870994