



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-11-26
Pictures	35
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-09
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	26
Total items failed	3

MOT #17	2024-02-08 12:28
MOT test number	497615395915
Result	✓ Passed
Next expiry date	2025-02-09
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2023-02-10 15:07
MOT test number	624554574783
Result	✓ Passed

MOT #15	2021-11-12 13:54
MOT test number	235468201030
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14	2021-03-22 14:05
MOT test number	774656784516
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13** 2020-03-14 15:16**MOT test number** 723197252910**Result** ✓ Passed**MOT #12** 2020-03-14 15:16**MOT test number** 345815171911**Result** ✗ Failed

Pass with rectification Offside Front Body component damaged and likely to cause injury lens (6.2.1 (a) (i))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #11 2019-03-24 13:56**MOT test number** 250790720091**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edges (5.2.3 (e))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side inner section (1.1.14 (a) (ii))

MOT #10 2019-03-24 13:15**MOT test number** 681533967721**Result** ✗ Failed

MAJOR Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edges (5.2.3 (e))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side inner section (1.1.14 (a) (ii))

**MOT #9** 2018-03-20 18:26**MOT test number** 108875988640**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2018-03-20 17:53**MOT test number** 142613304231**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2017-03-18 16:09**MOT test number** 452016456706**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #6** 2016-03-17 16:18**MOT test number** 834539030254**Result** ✓ Passed**Advice** Nearside Front wiper blade slight worn**Advice** Exhaust system corroding**Advice** Under tray fitted**Advice** Front Brake pad(s) wearing thin both sides (3.5.1g)**MOT #5** 2015-03-11 16:10**MOT test number** 656130775091**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-03-18 16:22**MOT test number** 729657474085**Result** ✓ Passed**MOT #3** 2013-03-21 11:40**MOT test number** 778920683093**Result** ✓ Passed**MOT #2** 2012-03-22 16:37**MOT test number** 749632482081**Result** ✓ Passed**MOT #1** 2011-04-15 16:20**MOT test number** 238445301406**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-28
Last registration	2024-02-08
Complete history	See info



Registration #1	2008-04-28	14 mi
Registration #2	2011-04-15	27.289 mi
Registration #3	2012-03-22	35.492 mi
Registration #4	2013-03-21	38.362 mi
Registration #5	2014-03-18	40.170 mi
Registration #6	2015-03-11	41.375 mi
Registration #7	2016-03-17	43.447 mi
Registration #8	2017-03-18	45.506 mi
Registration #9	2018-03-20	50.055 mi
Registration #10	2018-03-20	50.055 mi
Registration #11	2019-03-20	50.055 mi
Registration #12	2019-03-20	50.055 mi
Registration #13	2019-03-20	50.055 mi
Registration #14	2019-03-20	50.055 mi
Registration #15	2019-03-20	50.055 mi
Registration #16	2019-03-20	50.055 mi
Registration #17	2019-03-20	50.055 mi
Registration #18	2019-03-20	50.055 mi
Registration #19	2019-03-20	50.055 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZV011339