



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 S
Colour	Blue
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	120 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



MOT history

MOT #22 2020-08-27 15:33

MOT test number 669323771619

Result ✓ Passed

Next expiry date 2021-08-26

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Wiper Smeary
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #21**

2020-08-22 11:52

MOT test number

867668496703

Result**✗ Failed**

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt split (2.1.3 (g) (ii))
- Advice** Nearside wiper slight smear
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Fail** Power steering inoperative (2.1.5 (c) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
- Fail** Power steering component leaking (2.1.5 (a))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt split (2.1.3 (g) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Power steering fluid reservoir empty (2.1.5 (b) (ii))

MOT #20

2019-08-22 14:21

MOT test number

632113148434

Result**✓ Passed****MOT #19**

2019-08-22 12:56

MOT test number

375969269044

Result**✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #18** 2018-08-18 14:28**MOT test number** 793581392809**Result** ✓ Passed**MOT #17** 2018-08-18 13:29**MOT test number** 369546054402**Result** ✗ Failed**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #16** 2017-08-25 10:14**MOT test number** 243071943498**Result** ✓ Passed**MOT #15** 2017-08-24 11:21**MOT test number** 451473028033**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #14	2016-08-10 14:26
MOT test number	705130490106
Result	✓ Passed
Advice	Coolant leak from above gearbox area
Advice	Nearside Front Tyre worn close to the legal limit 2.2 mm (4.1.E.1)
Advice	Coolant level was very low (topped up)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Front Tyre worn close to the legal limit 3.4 mm (4.1.E.1)

MOT #13	2016-08-10 10:30
MOT test number	888780105395
Result	✗ Failed
Fail	Nearside Steering rack gaiter split (2.2.D.2d)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Front Tyre worn close to the legal limit 3.4 mm (4.1.E.1)
Advice	Coolant level was very low (topped up)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Offside Steering rack gaiter split (2.2.D.2d)
Advice	Nearside Front Tyre worn close to the legal limit 2.2 mm (4.1.E.1)
Advice	Coolant leak from above gearbox area

**MOT #12** 2015-07-27 10:00**MOT test number** 449448805202**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Old wiper damage to screen**Notice** Small hole in offside rack boot**Notice** Offside front trim under bumper is split**MOT #11** 2014-08-21 15:29**MOT test number** 218463734242**Result** ✓ Passed**MOT #10** 2014-08-21 14:59**MOT test number** 188563934247**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #9** 2013-08-13 11:04**MOT test number** 559075823262**Result** ✓ Passed**MOT #8** 2012-08-24 13:15**MOT test number** 939737032243**Result** ✓ Passed

**MOT #7** 2012-08-23 11:40**MOT test number** 548046532216**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #6** 2011-08-09 10:44**MOT test number** 575031921292**Result** ✓ Passed**MOT #5** 2010-08-26 10:16**MOT test number** 391878430234**Result** ✓ Passed**MOT #4** 2010-05-06 09:24**MOT test number** 271026120195**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-04-27 18:22**MOT test number** 690477619151**Result** ✓ Passed**MOT #2** 2008-03-10 10:09**MOT test number** 180190978492**Result** ✓ Passed



MOT #1	2007-03-13 10:01
MOT test number	144622377468
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	EK04YAW
Plate since	2024-03-29
Current registration	EK04YAW
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-30
Last registration	2020-08-27
Complete history	See info



Registration #1	2004-03-30	20 mi
Registration #2	2007-03-13	4.246 mi
Registration #3	2008-03-10	5.320 mi
Registration #4	2009-04-27	6.345 mi
Registration #5	2010-05-06	20.017 mi
Registration #6	2010-08-26	21.724 mi
Registration #7	2011-08-09	26.116 mi
Registration #8	2012-08-23	31.786 mi
Registration #9	2012-08-24	31.789 mi
Registration #10	2013-08-13	36.996 mi
Registration #11	2014-08-21	43.637 mi
Registration #12	2014-08-21	43.637 mi
Registration #13	2015-08-21	43.637 mi
Registration #14	2016-08-21	43.637 mi
Registration #15	2017-08-21	43.637 mi
Registration #16	2018-08-21	43.637 mi
Registration #17	2019-08-21	43.637 mi
Registration #18	2020-08-21	43.637 mi
Registration #19	2021-08-21	43.637 mi
Registration #20	2022-08-21	43.637 mi
Registration #21	2023-08-21	43.637 mi
Registration #22	2024-03-29	43.637 mi
Registration #23	2024-03-29	43.637 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FSR94900767