



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-14
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	19
Total items failed	14

MOT #15	2024-02-15 14:40
MOT test number	461451433186
Result	✓ Passed
Next expiry date	2025-02-14

MOT #14	2024-02-09 10:08
MOT test number	791590765937
Result	✗ Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Offside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Nearside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))

**MOT #13**

2023-02-09 11:46

MOT test number

370040722911

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge tyre wearing inner edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front bottom arm rear bushes slight play (5.3.4 (a) (i))**Advice** Undertrays fitted**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both rear arm bushes slight play (5.3.4 (a) (i))**MOT #12**

2023-02-09 09:49

MOT test number

768644398582

Result

✗ Failed

Fail Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Windscreen washer not working (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre wearing inner edge (5.2.3 (e))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both rear arm bushes slight play (5.3.4 (a) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Undertrays fitted**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front bottom arm rear bushes slight play (5.3.4 (a) (i))**MOT #11**

2022-02-11 10:24

MOT test number

141065096783

Result

✓ Passed

**MOT #10**

2022-02-10 13:53

MOT test number

157736513781

Result**✗ Failed****Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #9**

2021-10-27 12:32

MOT test number

163212363634

Result**✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake pipe corroded, covered in grease or other material offside front to rear (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #8**

2021-10-26 09:26

MOT test number

191529140600

Result**✗ Failed****Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material offside front to rear (1.1.11 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #7** 2020-10-06 09:32**MOT test number** 545887192009**Result** ✓ Passed**MOT #6** 2020-10-06 09:32**MOT test number** 228933004344**Result** ✗ Failed**Pass with rectification** Front Position lamp not working both (4.2.1 (a) (ii))**MOT #5** 2019-09-13 07:39**MOT test number** 946550175587**Result** ✓ Passed**MOT #4** 2018-02-19 09:40**MOT test number** 101058912485**Result** ✓ Passed**MOT #3** 2017-03-17 11:04**MOT test number** 187907339784**Result** ✓ Passed**MOT #2** 2017-03-17 11:04**MOT test number** 223877034004**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #1** 2016-03-31 10:53**MOT test number** 825985839609**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YG13OKN
Plate since	2019-03-28
Current registration	YG13OKN
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-27
Last registration	2024-02-15
Complete history	See info



Registration #1	2013-03-27	28 mi
Registration #2	2016-03-31	28.384 mi
Registration #3	2017-03-17	40.050 mi
Registration #4	2017-03-17	40.050 mi
Registration #5	2018-02-19	52.477 mi
Registration #6	2019-09-13	64.208 mi
Registration #7	2020-10-06	72.455 mi
Registration #8	2020-10-06	72.455 mi
Registration #9	2021-10-26	78.941 mi
Registration #10	2022-05-22	85.377 mi
Registration #11	2022-05-22	85.377 mi
Registration #12	2022-05-22	85.377 mi
Registration #13	2022-05-22	85.377 mi
Registration #14	2022-05-22	85.377 mi
Registration #15	2022-05-22	85.377 mi
Registration #16	2022-05-22	85.377 mi
Registration #17	2022-05-22	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ