



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | S40 S S40 |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 99 BHP |
| Max. torque | 150 Nm at 4.000 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.7 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 39.2 mpg |
| CO2 emission | 169 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-22 |
| Pictures | 1 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-08 |
| MOT pass rate | 71 % |
| MOT passed | 12 |
| Failed MOT tests | 5 |
| Total advice items | 55 |
| Total items failed | 10 |

| | |
|------------------|--|
| MOT #17 | 2023-10-02 09:50 |
| MOT test number | 238641344353 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-08 |
| Advice | Rear suspension arms corroded |
| Advice | Direction indicator slightly discoloured both rear (4.4.3 (a)) |
| Advice | Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |
| Advice | Offside Rear anti roll bar link corroded |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #16 | 2023-10-02 08:59 |
| MOT test number | 883114452718 |
| Result | ✗ Failed |
| Advice | Direction indicator slightly discoloured both rear (4.4.3 (a)) |
| Advice | Offside Rear anti roll bar link corroded |
| Fail | Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii)) |
| Advice | Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Rear suspension arms corroded |

**MOT #15**

2022-10-08 09:22

MOT test number

155985648775

Result

✓ Passed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14

2022-10-08 09:22

MOT test number

776856294808

Result

✗ Failed

- Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2021-10-09 11:23**MOT test number** 451233873237**Result** ✓ Passed**MOT #12** 2021-10-05 09:32**MOT test number** 139449862240**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened All four (1.1.14 (a) (ii))**Fail** Power steering pipe/hose leaking (2.1.5 (a))**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11** 2021-06-19 08:48**MOT test number** 351768271235**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both Discs (1.1.14 (a) (ii))**MOT #10** 2020-07-07 13:39**MOT test number** 880084989736**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #9**

2020-07-07 13:39

MOT test number

213744869413

Result**✗ Failed****Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8**

2019-06-13 10:58

MOT test number

647440968949

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #7**

2018-03-29 14:40

MOT test number

436699749128

Result**✓ Passed****MOT #6**

2017-07-08 11:32

MOT test number

578526859144

Result**✓ Passed****Advice** Nearside Front tyre inner edge worn**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front tyre inner edge worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2017-07-08 08:40**MOT test number** 946193266877**Result** ✗ Failed**Fail** Offside Front Front position lamp(s) incorrect colour (1.1.A.3e)**Advice** Offside Front tyre inner edge worn**Advice** Offside Rear Tyre worn close to the legal limit on 1.6 (legal limit) (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Front position lamp(s) incorrect colour (1.1.A.3e)**Advice** Nearside Front tyre inner edge worn**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2016-08-02 09:19**MOT test number** 118069334825**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre slightly misshapen**MOT #3** 2015-07-31 14:39**MOT test number** 157302615251**Result** ✓ Passed**MOT #2** 2014-12-15 09:41**MOT test number** 789079944360**Result** ✓ Passed



| | |
|-----------------|---|
| MOT #1 | 2013-12-12 09:55 |
| MOT test number | 138616043372 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 154 |
| MOT expiry date | 8 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2023-03-29 |
| Current registration | ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2010-12-31 |
| Last registration | 2023-10-02 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-12-31 | 19 mi |
| Registration #2 | 2013-12-12 | 14.417 mi |
| Registration #3 | 2014-12-15 | 18.884 mi |
| Registration #4 | 2015-07-31 | 20.446 mi |
| Registration #5 | 2016-08-02 | 33.388 mi |
| Registration #6 | 2017-07-08 | 46.651 mi |
| Registration #7 | 2017-07-08 | 46.652 mi |
| Registration #8 | 2018-03-29 | 56.085 mi |
| Registration #9 | 2019-06-13 | 67.048 mi |
| Registration #10 | 2020-07-07 | 75.281 mi |
| Registration #11 | 2020-07-07 | 75.281 mi |
| Registration #12 | 2020-07-07 | 75.281 mi |
| Registration #13 | 2020-07-07 | 75.281 mi |
| Registration #14 | 2020-07-07 | 75.281 mi |
| Registration #15 | 2020-07-07 | 75.281 mi |
| Registration #16 | 2020-07-07 | 75.281 mi |
| Registration #17 | 2020-07-07 | 75.281 mi |
| Registration #18 | 2020-07-07 | 75.281 mi |
| Registration #19 | 2020-07-07 | 75.281 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1322 kg |
| Max. allowed weight | 1800 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|-----------------|--------|
| Number of axles | 2 |
| Engine number | 203397 |