




General information

| | |
|---------------------|-----------------------------|
| Make | VAUXHALL |
| Model | GRANDLAND X ELITE NAV TURBO |
| Colour | Blue |
| Year of manufacture | 2020 |
| Top speed | 122 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 128 BHP |
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.199 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption combined | 45.6 mpg |
| CO2 emission | 142 g/km |
| CO2 label | F |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-05 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-24 |
| MOT pass rate | 100 % |
| MOT passed | 1 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #1 | 2023-09-25 15:18 |
| MOT test number | 951257180754 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-24 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords cut in tread (5.2.3 (d) (i)) |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 24 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  SH70PLZ |
| Plate since | 2019-06-29 |
| Current registration |  SH70PLZ |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 3 |
| First mileage registration | 2020-10-29 |
| Last registration | 2023-09-25 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2020-10-29 | 27 mi |
| Registration #2 | 2023-09-25 | 25,377 mi |
| Registration #3 | 2023-09-25 | 25,377 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 85% |
| Children | 84% |
| Pedestrian | 62% |
| Safety systems | 57% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1856 mm |
| Height | 1609 mm |
| Length | 4477 mm |
| Wheel base | 2604 mm |
| Kerb weight | 1350 kg |
| Max. allowed weight | 1900 kg |

Additional information

| | |
|--------------------|-------------------|
| Fuel tank capacity | 53 l |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 10TMA40089048 O3S |