



W95IRGC

report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER HARD-TOP TD5
Colour	Green
Year of manufacture	2000
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.3 mpg
Consumption extra urban	32.1 mpg
Consumption combined	32.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-01
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-04
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #5	2023-10-05 16:05
MOT test number	811258506329
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material near caliper (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material near caliper (1.1.11 (c))

MOT #4	2022-09-28 08:48
MOT test number	606185476317
Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #3** 2022-09-27 10:28**MOT test number** 880476345405**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #2** 2021-10-05 13:41**MOT test number** 155877037522**Result** ✓ Passed**MOT #1** 2021-04-22 10:57**MOT test number** 800281618400**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 October 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		4 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	W951RGC
Plate since	2024-03-29
Current registration	W951RGC
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2000-03-15
Last registration	2023-10-05
Complete history	See info



Registration #1	2000-03-15	26 mi
Registration #2	2021-04-22	64.916 mi
Registration #3	2021-10-05	69.866 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Dimensions & weight

Width	1790 mm
Length	3883 mm
Wheel base	2360 mm
Kerb weight	1695 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of axles	2
Engine number	10P90447A