





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Silver
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

F	n	t	r۱	,	2
_				,	_

Date	2021-10-07
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk

Entry 1

Date	2021-09-17
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-25
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #8	2023-09-26 10:10
MOT test number	249302215978
Result	✓ Passed
Next expiry date	2024-09-25

MOT #7	2023-09-26 09:40
MOT test number	396484197021
Result	× Failed
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	

MOT #6	2022-02-24 15:50
MOT test	number 275746367049
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a)
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a)
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/12



MOT #5 2022-02-24 15:50

MOT test number 857529369194

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MOT #4 2021-02-17 13:14

MOT test number 269309687626

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Tyre worn close to legal limit/worn on edge both sides getting low (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2020-02-18 14:06

MOT test number 228979207844

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2019-01-14 12:15

MOT test number 258715273938

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2018-06-13 11:14

MOT test number 178238627857

Result \rightarrow Passed

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Tyre worn close to legal limit/worn on edge Low tread (5.2.3 (e))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

EK15GVG

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HYUNDAI had different number plates. ober of plates

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



EK15GVG

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-26
Last registration	2023-09-26
Complete history	See info



Registration #1	2015-03-26	23 mi
Registration #2	2018-06-13	27.586 mi
Registration #3	2019-01-14	31.601 mi
Registration #4	2020-02-18	40.740 mi
Registration #5	2021-02-17	46.282 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.074
Registration #11		11.777 au

More info >

CarCheck.co.uk page 11/12



Car features

The HYUNDAI factory car options list is only available in the premium report.				

S0225 Air conditioning

S0295

S0482

S0501

\$0566 \$0567

S0569

View the complete HYUNDAI factory list for this vehicle <u>here</u>.

More info >

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number D4FDFZ359220