



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVTI GX
Colour	Red
Year of manufacture	2002
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	146 BHP
Max. torque	193 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-27
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-02-25
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	29
Total items failed	8

MOT #21	2022-02-26 11:14
MOT test number	701945288518
Result	✓ Passed
Next expiry date	2023-02-25
Advice	Under body corroded
Advice	Seat belt anchorage prescribed area is corroded but not considered excessive both inner sills and rear lower wheel arches (7.1.1 (a) (i))
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Advice	N/s/f wing damaged

**MOT #20** 2022-02-21 13:56**MOT test number** 546032867300**Result** ✗ Failed

- Advice** Under body corroded
- Fail** Nearside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Brake performance not tested (1.2.1 (g))
- Fail** Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** N/s/f wing damaged
- Fail** Brake pipe excessively corroded both front to rears (1.1.11 (c))
- Advice** Seat belt anchorage prescribed area is corroded but not considered excessive both inner sills and rear lower wheel arches (7.1.1 (a) (i))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #19** 2021-02-09 14:35**MOT test number** 437740108774**Result** ✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material feed to hose (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material feed to hose (1.1.11 (c))

**MOT #18** 2020-02-04 09:37**MOT test number** 267479445828**Result** ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material feeds to both sides (1.1.11 (c))

**MOT #17** 2020-02-04 09:37**MOT test number** 412124782407**Result** ✗ Failed**Advice** Rear Brake pipe corroded, covered in grease or other material feeds to both sides (1.1.11 (c))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #16** 2019-02-04 09:57**MOT test number** 368085522359**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material feed to hose (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material feed to hose (1.1.11 (c))**MOT #15** 2018-01-31 09:34**MOT test number** 624666663869**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded feed to hose (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded feed to hose (3.6.B.2c)**MOT #14** 2017-02-03 09:28**MOT test number** 714167785631**Result** ✓ Passed**MOT #13** 2016-02-08 09:38**MOT test number** 316442098085**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pipe slightly corroded both feeds to flex (3.6.B.2c)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12** 2015-02-07 11:58**MOT test number** 819688135090**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-02-12 08:27**MOT test number** 175603044402**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-02-11 17:03**MOT test number** 595462844052**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-05-07 10:19**MOT test number** 137057723139**Result** ✓ Passed**Notice** Hi level brake lamp inop**MOT #8** 2012-05-22 09:17**MOT test number** 908343342141**Result** ✓ Passed

**MOT #7** 2011-05-27 11:39**MOT test number** 805037341166**Result** ✓ Passed**MOT #6** 2011-05-27 11:39**MOT test number** 955067041108**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2010-06-07 15:09**MOT test number** 601098750109**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2009-04-15 09:35**MOT test number** 524405509196**Result** ✓ Passed**Advice** Front brake juddering slightly (3.7.A.2b)**MOT #3** 2008-04-07 13:34**MOT test number** 301728498037**Result** ✓ Passed**MOT #2** 2007-04-17 15:06**MOT test number** 924917007100**Result** ✓ Passed**MOT #1** 2006-04-27 14:17**MOT test number** 223797516466**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 June 2023

X

MOT

Expired:  
25 February 2023

Tax status	Expired at 1 June 2023
Days left	333 days too late
MOT expiry date	25 February 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-10-11
Last registration	2022-02-26
Complete history	<a href="#">See info</a>



Registration #1	2002-10-11	7 mi
Registration #2	2006-04-27	19.796 mi
Registration #3	2007-04-17	24.864 mi
Registration #4	2008-04-07	29.854 mi
Registration #5	2009-04-15	35.209 mi
Registration #6	2010-06-07	40.077 mi
Registration #7	2011-05-27	47.071 mi
Registration #8	2012-05-22	54.076 mi
Registration #9	2013-05-07	61.194 mi
Registration #10	2014-02-11	68.593 mi
Registration #11	2014-02-12	68.593 mi
Registration #12	2015-05-20	75.277 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2017-05-20	75.277 mi
Registration #15	2018-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2020-05-20	75.277 mi
Registration #18	2021-05-20	75.277 mi
Registration #19	2022-05-20	75.277 mi
Registration #20	2023-05-20	75.277 mi
Registration #21	2024-05-20	75.277 mi
Registration #22	2025-05-20	75.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ0898312