





General information

| Make | MAZDA |
|---------------------|-------------------|
| Model | 6 D SPORT NAV |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 134 mph |
| 0 - 60 mph | 8.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 173 BHP |
|-------------------------|---------------------|
| Max. torque | 420 Nm at 2.000 rpm |
| Engine capacity | 2.191 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |







Internet history

Entry 2

Date

Pictures

2022-10-30

9

Listing price

View report



source: cargurus.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-02-01 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-10-24 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 3 |

| MOT #6 | 2023-10-25 13:08 |
|------------------|------------------|
| MOT test number | 641481103439 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-24 |

| MOT #5 | | 2023-10-25 13:08 |
|-------------------------|---|------------------|
| MOT test number | | 810126954907 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Front Road wheel fixing missing (5.2.1 (a) (i)) | |
| Pass with rectification | Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) | |
| Pass with rectification | Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |

| MOT #4 | 2022-03-18 08:19 |
|-----------------|------------------|
| MOT test number | 467264981111 |
| Result | ✓ Passed |

| МОТ #3 | 2021-03-19 17:16 |
|-----------------|------------------|
| MOT test number | 670726267858 |
| Result | ✓ Passed |





| MOT #2 | | 2019-12-20 10:39 |
|--|--|------------------|
| MOT test | number | 939697225297 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| | | |
| MOT #1 | | 2019-01-11 08:56 |
| MOT test | number | 822983109499 |
| Result | | ✓ Passed |
| Advice | Nearside Front fog lamp loose | |
| Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |



Tax & MOT check

| X Untaxed Tax expired: 19 March 2024 | ✓ MOT Expires: 24 October 2024 |
|---|---|
| Tax status | Expired at 19 March 2024 |
| Days left | 41 days too late |
| MOT expiry date | 24 October 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2016-01-20 |
| Last registration | 2023-10-25 |
| Complete history | See info |



| Registration #1 | 2016-01-20 | 17 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-01-11 | 56.380 mi |
| Registration #3 | 2019-12-20 | 71.926 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | 2021-03-19 | 81.872 mi |
| Registration #6 | | 11.117 est |
| Registration #7 | | 11.117 esi |
| Registration #8 | | 11.117 esi |
| Registration #9 | | 10.000 mi |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 92% |
| Children | 77% |
| Pedestrian | 66% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | <u>see crash video</u> |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1840 mm |
| Height | 1450 mm |
| Length | 4870 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1430 kg |
| Max. allowed weight | 2110 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 62 I |
| | 62 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |