



report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | VOLVO             |
| Model               | V50 T5 SE V50     |
| Colour              | Green             |
| Year of manufacture | 2004              |
| Top speed           | 146 mph           |
| 0 - 60 mph          | 6.8 seconds       |
| Gearbox             | 5 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 220 BHP             |
| Max. torque             | 320 Nm at 1.500 rpm |
| Engine capacity         | 2.521 cc            |
| Cylinders               | 5                   |
| Fuel type               | Petrol              |
| Consumption city        | 20.8 mpg            |
| Consumption extra urban | 39.8 mpg            |
| Consumption combined    | 29.7 mpg            |
| CO2 emission            | 227 g/km            |
| CO2 label               | L                   |





## Internet history

### Entry 3

Date 2021-12-05

Pictures 50

Listing price [View report](#)



source: cargurus.co.uk

### Entry 2

Date 2021-08-19

Pictures 55

Listing price [View report](#)




source: yesauto.com

### Entry 1

Date 2021-08-05

Pictures 50

Listing price [View report](#)



source: cargurus.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-12-21 |
| MOT pass rate      | 63 %       |
| MOT passed         | 19         |
| Failed MOT tests   | 11         |
| Total advice items | 54         |
| Total items failed | 15         |

|                  |                  |
|------------------|------------------|
| MOT #30          | 2023-12-19 12:22 |
| MOT test number  | 918795293524     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-12-21       |
| Advice           | Exhaust corroded |

|                 |  |
|-----------------|--|
| MOT #29         | 2023-12-13 09:25   |
| MOT test number | 523443464470   |
| Result          | ✗ Failed   |
| Advice          | Both front tyres bald on inner edges                               |
| MAJOR           | Offside Stop lamp(s) not working (4.3.1 (a) (ii))                  |
| MAJOR           | Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))       |
| Advice          | Exhaust corroded   |
| MAJOR           | Driver's door cannot be opened from inside the vehicle (6.2.3 (a)) |
| DANGEROUS       | Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))       |

**MOT #28** 2022-12-19 13:44**MOT test number** 190749009502**Result** ✓ Passed**Advice** Exhaust corroded**Advice** Nearside rear tyre worn on inner edge**MOT #27** 2022-12-19 09:01**MOT test number** 197154918791**Result** ✗ Failed**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside rear tyre worn on inner edge**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Exhaust corroded**MOT #26** 2021-12-22 16:14**MOT test number** 605238776626**Result** ✓ Passed**MOT #25** 2021-03-04 15:57**MOT test number** 716430508154**Result** ✓ Passed**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #24** 2021-03-01 16:58**MOT test number** 534549354545**Result** ✗ Failed**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MAJOR** Headlamp levelling device inoperative both side (4.1.5 (a))**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Headlamp aim too high both side (4.1.2 (a))**MOT #23** 2020-03-11 09:58**MOT test number** 253290261398**Result** ✓ Passed**MOT #22** 2019-03-15 15:30**MOT test number** 929944950957**Result** ✓ Passed**MOT #21** 2018-03-23 18:08**MOT test number** 617373955729**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**MOT #20** 2018-03-22 17:56**MOT test number** 653114098168**Result** ✗ Failed**Fail** Nearside Front Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm INNER SHOULDER (4.1.E.1)

**MOT #19** 2017-07-12 09:22**MOT test number** 707586069808**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit INNER SHOULDER 205 50 17 (4.1.E.1)**Advice** TRACKING REQUIRED**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #18** 2017-07-11 13:54**MOT test number** 796252156089**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** TRACKING REQUIRED**Fail** Offside Front Lower Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front Tyre worn close to the legal limit INNER SHOULDER 205 50 17 (4.1.E.1)**MOT #17** 2016-11-12 10:07**MOT test number** 249398666438**Result** ✓ Passed**MOT #16** 2016-06-30 18:33**MOT test number** 439693534398**Result** ✓ Passed**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #15** 2015-07-07 14:27**MOT test number** 855188685145**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Offside front tyre worn on inner and outer edge**Notice** Nearside front tyre sidewall damage**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2015-07-07 10:51**MOT test number** 648818885114**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Nearside front tyre sidewall damage**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Offside front tyre worn on inner and outer edge**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #13** 2014-06-26 14:26**MOT test number** 778677574163**Result** ✓ Passed

**MOT #12** 2014-06-26 09:09**MOT test number** 517487474146**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2013-06-12 14:35**MOT test number** 259373563135**Result** ✓ Passed**MOT #10** 2013-06-12 14:35**MOT test number** 568443463113**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2012-06-19 10:44**MOT test number** 186501172142**Result** ✓ Passed**MOT #8** 2012-06-15 10:53**MOT test number** 258087562427**Result** ✗ Failed**Fail** Offside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Stop lamp not working (1.2.1b)



**MOT #7** 2011-06-08 09:46**MOT test number** 695379251173**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2010-06-17 10:12**MOT test number** 962598660142**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/S/R tyre, sidewall perishing
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-06-17 10:12**MOT test number** 570518660138**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/S/R tyre, sidewall perishing

**MOT #4** 2009-03-19 15:06**MOT test number** 142068779475**Result** ✓ Passed**Notice** Puncher N/S/R tyre**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Rear number plate slightly faded/deteriorated**Notice** Front number plate slightly faded**MOT #3** 2008-03-14 11:15**MOT test number** 732424678025**Result** ✓ Passed**Notice** Rear number plate slightly deteriorated**Notice** Hand brake has travel**MOT #2** 2007-03-15 08:54**MOT test number** 740014277042**Result** ✓ Passed**MOT #1** 2007-03-15 08:54**MOT test number** 434134177077**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
21 December 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 June              |
| <b>Days left</b>        | 34                              |
| <b>MOT expiry date</b>  | 21 December 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | K          |
| <b>Single payment (12 months)</b>              | £ 395,00,- |
| <b>Single six month payment</b>                | £ 217,25,- |
| <b>Total payable by 12 monthly instalments</b> | £ 414,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>OV04EEB</b> |
| Plate since          | 2019-09-29   |
| Current registration |  <b>OV04EEB</b> |
| Plate since          | 2019-09-29   |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 31                       |
| First mileage registration | 2004-03-19               |
| Last registration          | 2023-12-19               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2004-03-19 | 28 mi     |
| Registration #2  | 2007-03-15 | 10.269 mi |
| Registration #3  | 2008-03-14 | 14.633 mi |
| Registration #4  | 2009-03-19 | 18.211 mi |
| Registration #5  | 2010-06-17 | 27.720 mi |
| Registration #6  | 2011-06-08 | 36.906 mi |
| Registration #7  | 2012-06-15 | 45.457 mi |
| Registration #8  | 2012-06-19 | 45.535 mi |
| Registration #9  | 2013-06-12 | 54.373 mi |
| Registration #10 | 2014-06-26 | 64.296 mi |
| Registration #11 | 2014-06-26 | 64.302 mi |
| Registration #12 | 2015-07-07 | 76.946 mi |
| Registration #13 | 2015-07-07 | 76.946 mi |
| Registration #14 | 2016-06-30 | 83.115 mi |
| Registration #15 | 2016-11-12 | 85.075 mi |
| Registration #16 | 2017-07-11 | 89.435 mi |
| Registration #17 | 2018-06-20 | 95.557 mi |
| Registration #18 | 2019-06-20 | 95.557 mi |
| Registration #19 | 2020-06-20 | 95.557 mi |
| Registration #20 | 2021-06-20 | 95.557 mi |
| Registration #21 | 2022-06-20 | 95.557 mi |
| Registration #22 | 2023-06-20 | 95.557 mi |
| Registration #23 | 2024-06-20 | 95.557 mi |
| Registration #24 | 2025-06-20 | 95.557 mi |
| Registration #25 | 2026-06-20 | 95.557 mi |
| Registration #26 | 2027-06-20 | 95.557 mi |



|                  |            |            |
|------------------|------------|------------|
| Registration #27 | 2025-25-25 | 25,252 442 |
| Registration #28 | 2025-25-25 | 25,252 442 |
| Registration #29 | 2025-25-25 | 25,252 442 |
| Registration #30 | 2025-25-25 | 25,252 442 |
| Registration #31 | 2025-25-25 | 25,252 442 |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 1770 mm |
| Height      | 1452 mm |
| Length      | 4514 mm |
| Wheel base  | 2640 mm |
| Kerb weight | 1526 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of axles    | 2                     |
| Engine number      | 3353527               |