



MF57YMO

report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-18
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	33
Total items failed	33

MOT #24	2024-02-28 13:35
MOT test number	329373803127
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Dipstick mounting damaged
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #23**

2024-02-22 14:39

MOT test number

591125326914

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Front Headlamp lens slightly defective cloudy (4.1.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Dipstick mounting damaged**MOT #22**

2023-02-18 10:54

MOT test number

729680074973

Result**✓ Passed****MOT #21**

2022-01-22 15:19

MOT test number

568336837757

Result**✓ Passed****Advice** Nearside Front Bumper mountings corroded but not likely to become detached damage (6.1.4 (a) (i))**Advice** Steering box has seepage (2.1.1 (e) (i))**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20** 2022-01-21 11:49**MOT test number** 840073370943**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Nearside Front Bumper mountings corroded but not likely to become detached damage (6.1.4 (a) (i))
- Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Steering box has seepage (2.1.1 (e) (i))

MOT #19 2021-01-25 17:55**MOT test number** 820287651520**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration damaged but not likely to be misread
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2019-06-11 16:00**MOT test number** 839300159479**Result** ✓ Passed

**MOT #17**

2019-06-11 11:14

MOT test number

587302820979

Result**✗ Failed****Fail** Rear Exhaust system insecure (6.1.2 (a))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Coolant level low**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16**

2018-06-12 15:41

MOT test number

867842152012

Result**✓ Passed****MOT #15**

2018-06-11 11:40

MOT test number

759443954918

Result**✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Emissions not tested Oil level low (8.2.2.2 (e))**Fail** Fuel system component leaking excessively or a risk of fire (6.1.3 (b) (ii))**Advice** Coolant level low**Fail** Windscreen washer not working (3.5 (a))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14** 2017-06-12 13:02**MOT test number** 821048951857**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2017-06-12 08:46**MOT test number** 751727779686**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #12** 2016-06-16 16:02**MOT test number** 889304745185**Result** ✓ Passed

**MOT #11** 2016-06-15 09:11**MOT test number** 942941049309**Result** ✗ Failed**Fail** Nearside Headlamp aim too high and too far to the right. (1.8)**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Headlamp insecure (1.7.3)**MOT #10** 2015-06-15 17:04**MOT test number** 427936165193**Result** ✓ Passed**MOT #9** 2015-06-15 12:38**MOT test number** 336926665158**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Emissions not tested (7.4.B.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2014-06-13 12:43**MOT test number** 906974864115**Result** ✓ Passed

**MOT #7** 2014-06-13 12:43**MOT test number** 296864464403**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2013-06-11 14:50**MOT test number** 619922763144**Result** ✓ Passed**MOT #5** 2013-06-10 11:33**MOT test number** 118761163101**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear reflector missing (1.5.1a)**MOT #4** 2012-06-07 15:18**MOT test number** 727579652103**Result** ✓ Passed**MOT #3** 2012-06-07 09:34**MOT test number** 248339552445**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2011-06-16 15:17
MOT test number	168957861139
Result	✓ Passed
MOT #1	2010-09-03 10:13
MOT test number	913656640242
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	27 February 2025
Full MOT history	See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-09-21
Last registration	2024-02-28
Complete history	See info



Registration #1	2007-09-21	27 mi
Registration #2	2010-09-03	30.858 mi
Registration #3	2011-06-16	32.166 mi
Registration #4	2012-06-07	41.803 mi
Registration #5	2012-06-07	41.803 mi
Registration #6	2013-06-10	53.265 mi
Registration #7	2013-06-11	53.265 mi
Registration #8	2014-06-13	64.062 mi
Registration #9	2015-06-15	74.303 mi
Registration #10	2015-06-15	74.303 mi
Registration #11	2016-06-15	84.010 mi
Registration #12	2016-06-16	84.010 mi
Registration #13	2017-06-12	94.144 mi
Registration #14	2018-06-12	104.288 mi
Registration #15	2018-06-12	104.288 mi
Registration #16	2019-06-12	114.432 mi
Registration #17	2019-06-12	114.432 mi
Registration #18	2020-06-12	124.576 mi
Registration #19	2020-06-12	124.576 mi
Registration #20	2021-06-12	134.720 mi
Registration #21	2021-06-12	134.720 mi
Registration #22	2022-06-12	144.864 mi
Registration #23	2022-06-12	144.864 mi
Registration #24	2023-06-12	155.008 mi
Registration #25	2024-02-28	165.152 mi



Dimensions & weight

Width	2194 mm
Length	4805 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JB500025076