





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T2 MOMENTUM
Colour	Silver
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	220 Nm at 1.200 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	2.8 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/10




Internet history


Entry 1

Date 2021-07-31

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2024-07-27
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	3
Total items failed	0

MOT #4	2023-07-28 17:07
MOT test number	604619443670
Result	✓ Passed
Next expiry date	2024-07-27
Advice Rear Tyre slightly damaged/cracking or perishing n/s and o/s (5.2.3 (d) (ii))	

MOT #3		2023-07-28 14:21
MOT test	number	398156587282
Result		X Failed
Advice	Rear Tyre slightly damaged/cracking or perishing n/s and o/s (5.2.3 (d) (ii))	
MAJOR	Brake pedal has insufficient reserve travel (1.1.2 (a))	

MOT #2	2022-07-08 14:09
MOT test number	613191927249
Result	✓ Passed
MOT #1	2021-07-22 09:56
MOT test number	807907406166
Result	✓ Passed

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner	la : a b a
UWNEr	INISTARV
OWITCH	IIISCOLY

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NIA.
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-12-28
Last registration	2023-07-28
Complete history	See info



Registration #1	2018-12-28	7 mi
Registration #2	2021-07-22	13.705 mi
Registration #3		11,777 mi
Registration #4		71.777 es
Registration #5		71,777 es
Devictor #6		

Registration #6

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1393 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/

Number of axles 2

Engine number 2630091