




report date: 2024-03-29

General information

Make	KIA
Model	RIO DOMINO
Colour	White
Year of manufacture	2011
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





**Internet history**

**Entry 1**

Date	2021-05-24
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-01
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	36
Total items failed	13

**MOT #16** 2023-06-22 09:22

MOT test number 971394493177

Result ✓ Passed

Next expiry date 2024-07-01

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2023-06-22 09:22

MOT test number 678396221440

Result ✗ Failed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14** 2022-06-24 11:24

MOT test number 388838917142

Result ✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2021-07-01 10:00

MOT test number 494116745306

Result ✓ Passed



<b>MOT #12</b>	2021-06-29 10:49
<b>MOT test number</b>	403882880450
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Front Exhaust mounting defective (6.1.2 (a))
<b>Fail</b>	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Fail</b>	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Fail</b>	Central Exhaust system insecure missing (6.1.2 (a))

<b>MOT #11</b>	2020-07-02 15:31
<b>MOT test number</b>	761111839159
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2020-06-23 08:33
<b>MOT test number</b>	652121968585
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge 3mm + bald inner (5.2.3 (e))
<b>Fail</b>	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge 2mm + bald inner (5.2.3 (e))

<b>MOT #9</b>	2019-06-25 12:56
<b>MOT test number</b>	328801409993
<b>Result</b>	✓ Passed



<b>MOT #8</b>	2019-06-25 08:08
<b>MOT test number</b>	693957840083
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #7</b>	2018-06-23 10:33
<b>MOT test number</b>	344097644760
<b>Result</b>	✓ Passed
<b>Advice</b>	Centre exhaust bracket broken but still adequately secure
<b>Minor</b>	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge 185/65/14 (5.2.3 (e))
<b>Minor</b>	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))



MOT #6 2018-06-23 08:38

MOT test number 154724702819

Result ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 185/65/14 (5.2.3 (e))
- Fail** Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Centre exhaust bracket broken but still adequately secure
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #5 2017-06-23 11:46

MOT test number 778856415759

Result ✓ Passed

- Advice** N/s/r tyre perished
- Advice** O/s/r tyre perished
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust centre bracket broken
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #4** 2017-06-23 08:43

**MOT test number** 438976481840

**Result** ✗ Failed

- Advice** Exhaust centre bracket broken
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** N/s/r tyre perished
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** O/s/r tyre perished
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #3** 2016-06-22 10:01

**MOT test number** 317918761706

**Result** ✓ Passed

- Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Both rear tyres worn unevenly

**MOT #2** 2015-06-18 16:31

**MOT test number** 666539965131

**Result** ✓ Passed

- Notice** Front tyres wearing on inner edges
- Notice** Rear tyres losing shape

**MOT #1** 2014-06-28 08:33

**MOT test number** 266829674420

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 March 2025

✓  
**MOT**

**Expires:**  
1 July 2024

**Tax status** Valid until 1 March

**Days left** 305

**MOT expiry date** 1 July 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>FP11UYY</b>
Plate since	2024-03-29
Current registration	<b>FP11UYY</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	18
<b>First mileage registration</b>	2011-06-21
<b>Last registration</b>	2023-06-22
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2011-06-21	23 mi
<b>Registration #2</b>	2014-06-28	15.505 mi
<b>Registration #3</b>	2015-06-18	25.089 mi
<b>Registration #4</b>	2016-06-22	34.192 mi
<b>Registration #5</b>	2017-06-23	44.536 mi
<b>Registration #6</b>	2017-06-23	44.536 mi
<b>Registration #7</b>	2018-06-23	52.942 mi
<b>Registration #8</b>	2018-06-23	52.943 mi
<b>Registration #9</b>	2019-06-25	61.671 mi
<b>Registration #10</b>	2019-06-25	61.671 mi
<b>Registration #11</b>	2019-06-25	61.671 mi
<b>Registration #12</b>	2019-06-25	61.671 mi
<b>Registration #13</b>	2019-06-25	61.671 mi
<b>Registration #14</b>	2019-06-25	61.671 mi
<b>Registration #15</b>	2019-06-25	61.671 mi
<b>Registration #16</b>	2019-06-25	61.671 mi
<b>Registration #17</b>	2019-06-25	61.671 mi
<b>Registration #18</b>	2019-06-25	61.671 mi

[More info >](#)



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1244 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

G4EEAH382395