



**SY57MFV**

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SOVEREIGN
Colour	Silver
Year of manufacture	2007
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	331 Nm at 1.800 rpm
Engine capacity	2.099 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 2


Date	2022-01-19
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-05
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2023-07-14
<b>MOT pass rate</b>	68 %
<b>MOT passed</b>	13
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	82
<b>Total items failed</b>	14

<b>MOT #19</b>	2022-07-15 09:04
<b>MOT test number</b>	681739118174
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-07-14
<b>Advice</b>	Offside Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
<b>Advice</b>	Nearside Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
<b>Minor</b>	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #18</b>	2021-07-15 10:09
<b>MOT test number</b>	498105179967
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
<b>Advice</b>	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
<b>Advice</b>	Offside Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

**MOT #17**

2021-04-24 10:36

**MOT test number**

307931229583

**Result****✗ Failed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases front of centre section (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Exhaust back box clamp broken
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Handbrake effort poor
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))



MOT #16

2020-05-16 13:43

MOT test number

821110194513

Result		✓ Passed
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Inner and outer sill section corroded	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Multiple component/structure corroded underside of vehicle	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Inner and outer sill section corroded	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



MOT #15

2020-05-16 11:13

MOT test number

346264184871

Result

✖ Failed

- Fail

Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))
- Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Offside Inner and outer sill section corroded
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Nearside Inner and outer sill section corroded
- Advice

Multiple component/structure corroded underside of vehicle
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #14

2019-05-31 13:26

MOT test number

412291119930

Result		✓ Passed
Advice	Offside sill sections corroded	
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Rear axle trailing arm body mount bush (5.3.4 (a) (i))	
Advice	Nearside sill sections corroded	
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Brake pedal soft but holding pressure	

**MOT #13**

2019-05-17 14:02

**MOT test number**

585566841035

**Result**

✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Rear axle trailing arm body mount bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Brake pedal soft but holding pressure
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside sill sections corroded
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn Rear axle trailing arm body mount bush (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside sill sections corroded
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction mascot mirror (3.1 (a) (ii))

**MOT #12**

2018-06-01 14:04

**MOT test number**

966918243033

**Result**

✓ Passed



**MOT #11** 2018-05-29 14:49**MOT test number** 634329868395**Result** ✗ Failed

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

**MOT #10** 2017-03-28 13:11**MOT test number** 597745964130**Result** ✓ Passed

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

**MOT #9** 2016-04-12 08:45**MOT test number** 670745612770**Result** ✓ Passed

**Advice** Engine covers and under trays

**Advice** Nearside Rear Tyre worn close to the legal limit inner and outer edge (4.1.E.1)

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Offside Rear Tyre worn close to the legal limit inner and outer edge (4.1.E.1)

**MOT #8** 2016-04-12 08:45**MOT test number** 360327393639**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit inner and outer edge (4.1.E.1)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit inner and outer edge (4.1.E.1)**Advice** Engine covers and under trays**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2015-04-14 11:24**MOT test number** 675014705177**Result** ✓ Passed**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**MOT #6** 2014-04-14 16:10**MOT test number** 648694904167**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Noise from auxillary drive area

**MOT #5** 2014-04-14 16:10**MOT test number** 827544204121**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Noise from auxillary drive area**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #4** 2013-04-22 14:47**MOT test number** 289722713481**Result** ✓ Passed**MOT #3** 2012-09-13 15:48**MOT test number** 698597852287**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2011-09-13 16:37**MOT test number** 315246551455**Result** ✓ Passed**Notice** Advise brake pedal slightly spongy**Notice** Nearside front and offside front brake discs slightly worn**MOT #1** 2010-09-15 10:59**MOT test number** 862948050208**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 January 2023

✕  
MOT

Expired:  
14 July 2023

Tax status	Expired at 31 January 2023
Days left	455 days too late
MOT expiry date	14 July 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX


More info >





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-28
Last registration	2022-07-15
Complete history	<a href="#">See info</a>



Registration #1	2007-09-28	15 mi
Registration #2	2010-09-15	19.121 mi
Registration #3	2011-09-13	26.934 mi
Registration #4	2012-09-13	34.167 mi
Registration #5	2013-04-22	36.785 mi
Registration #6	2014-04-14	45.575 mi
Registration #7	2015-04-14	56.151 mi
Registration #8	2016-04-12	59.307 mi
Registration #9	2016-04-12	59.307 mi
Registration #10	2017-03-28	60.472 mi
Registration #11	2018-05-29	61.292 mi
Registration #12	2019-05-29	61.292 mi
Registration #13	2019-05-29	61.292 mi
Registration #14	2019-05-29	61.292 mi
Registration #15	2019-05-29	61.292 mi
Registration #16	2019-05-29	61.292 mi
Registration #17	2019-05-29	61.292 mi
Registration #18	2019-05-29	61.292 mi
Registration #19	2019-05-29	61.292 mi
Registration #20	2019-05-29	61.292 mi
Registration #21	2019-05-29	61.292 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	0607050110016G