



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-06
Pictures	22
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-10
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	46
Total items failed	25

MOT #20	2023-05-11 13:52
MOT test number	499878810361
Result	✓ Passed
Next expiry date	2024-06-10
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #19	2023-05-11 08:43
MOT test number	590097021308
Result	✗ Failed
Fail	Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #18** 2022-05-14 09:39**MOT test number** 808310181389**Result** ✓ Passed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front both front wish bone bushes perishing**Advice** Rear axle corroded**MOT #17** 2021-06-11 09:50**MOT test number** 169571678734**Result** ✓ Passed**MOT #16** 2021-06-07 15:15**MOT test number** 418638203821**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #15** 2020-09-16 14:39**MOT test number** 345267403387**Result** ✓ Passed

- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2019-08-29 13:32**MOT test number** 951395367060**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2019-08-28 09:54**MOT test number** 156323671608**Result** ✗ Failed

- Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure 235/40/18 (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #12 2018-09-07 12:55**MOT test number** 147487497962**Result** ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #11** 2018-09-07 09:52**MOT test number** 345717015245**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Offside Rear Suspension arm pin or bush likely to become detached trailing arm (5.3.4 (a) (ii))**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #10** 2017-09-11 12:11**MOT test number** 923647956810**Result** ✓ Passed**Advice** Eml light on**MOT #9** 2017-09-08 14:43**MOT test number** 243832066473**Result** ✗ Failed**Advice** Eml light on**Fail** Headlamp aim beam image obviously incorrect both (1.8.A.1b)**Fail** Central Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Rear Inner Tyre worn close to the legal limit edge (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement both (2.4.G.2)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

**MOT #8** 2016-09-14 11:13**MOT test number** 359046835036**Result** ✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2015-09-17 13:41**MOT test number** 428157581092**Result** ✓ Passed

Advice Front tyres low tread on inner edges

MOT #6 2015-09-17 10:17**MOT test number** 230868598588**Result** ✗ Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front tyres low tread on inner edges

Fail Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2014-08-28 16:50**MOT test number** 245820444285**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** O/s/r tyre low tread on inner edge**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-08-28 13:41**MOT test number** 477200644257**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** O/s/r tyre low tread on inner edge

**MOT #3** 2013-09-19 14:43**MOT test number** 935332363289**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** N/s/r tyre uneven wear on inner edge**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-09-19 09:57**MOT test number** 305372463245**Result** ✗ Failed**Notice** N/s/r tyre uneven wear on inner edge**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Emissions not tested (7.0)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2012-09-05 17:13**MOT test number** 305509342461**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	CU59LXV
Plate since	2019-03-28
Current registration	CU59LXV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-09-03
Last registration	2023-05-11
Complete history	See info



Registration #1	2009-09-03	12 mi
Registration #2	2012-09-05	25.149 mi
Registration #3	2013-09-19	36.965 mi
Registration #4	2013-09-19	36.965 mi
Registration #5	2014-08-28	48.343 mi
Registration #6	2014-08-28	48.343 mi
Registration #7	2015-09-17	62.929 mi
Registration #8	2015-09-17	62.929 mi
Registration #9	2016-09-14	76.477 mi
Registration #10	2017-09-08	86.630 mi
Registration #11	2017-09-11	86.635 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi
Registration #20	2019-05-20	95.277 mi
Registration #21	2019-05-20	95.277 mi
Registration #22	2019-05-20	95.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9B03425