





General information

| Make | CITROEN |
|---------------------|----------------------|
| Model | C4 PURETECH PLATINUM |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 108 mph |
| 0 - 60 mph | 12.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 81 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |







Internet history

Entry 1

Date

Pictures

2022-06-23

6

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-07-30 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 2 |

| MOT #8 | | 2023-07-31 12:45 |
|------------------|---|------------------|
| MOT test numbe | er | 657302039643 |
| Result | | 🗸 Passed |
| Next expiry date | 2 | 2024-07-30 |
| Advice Front | Exhaust has a minor leak of exhaust gases flexi joint (6.1.2 (a)) | |
| Advice Rear | Coil spring corroded Both (5.3.1 (b) (i)) | |
| Advice Front | Exhaust mounting defective Requires attention soon (6.1.2 (a)) | |

MOT #7

| Result | × Failed |
|---------------|--|
| Fail W | (indscreen washer not working (3.5 (a)) |
| Advice | Front Exhaust mounting defective Requires attention soon (6.1.2 (a)) |
| Advice | Front Exhaust has a minor leak of exhaust gases flexi joint (6.1.2 (a)) |
| Advice | Rear Coil spring corroded Both (5.3.1 (b) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge nail in tread/badly age cracked (5.2.3 (e)) |

| MOT #6 | 2022-07-26 15:40 |
|-----------------|------------------|
| MOT test number | 764201969767 |
| Result | ✓ Passed |

2023-07-31 10:18 335028324415





| MOT #5 | | 2022-02-04 10:00 |
|----------|---|------------------|
| MOT test | number | 419560994836 |
| Result | | Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) | |

| MOT #4 | 2021-03-01 10:15 |
|----------|--|
| MOT test | number 704988694568 |
| Result | ✓ Passed |
| Advice | Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| МОТ #3 | 2020-03-16 10:12 |
|--|------------------|
| MOT test number | 568095715143 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Rear Nail in tyre | |

| MOT #2 | 2020-03-16 09:47 |
|---|------------------|
| MOT test number | 678806554807 |
| Result | × Failed |
| Advice Nearside Rear Nail in tyre | |
| Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |





| MOT #1 | 2019-04-08 09:46 |
|--|------------------|
| MOT test number | 883577420910 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 | (e)) |



Tax & MOT check

| ✓ Taxed Tax due: 1 September 2024 | MOT Expires: 30 July 2024 |
|--|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 30 July 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 10 |
| First mileage registration | 2016-06-30 |
| Last registration | 2023-07-31 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-06-30 | 23 mi |
|------------------|------------|------------|
| Registration #2 | 2019-04-08 | 28.266 mi |
| Registration #3 | 2020-03-16 | 38.406 mi |
| Registration #4 | 2020-03-16 | 38.406 mi |
| Registration #5 | 2021-03-01 | 47.115 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 10.000 est |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1728 mm |
| Height | 1514 mm |
| Length | 3944 mm |
| Wheel base | 2451 mm |
| Kerb weight | 975 kg |
| Max. allowed weight | 1525 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 50 |
| | 50 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |