





report date: 2024-03-28

## General information

Make	RENAULT
Model	CAPTUR GT LINE TCE
Colour	Red
Year of manufacture	2019
Top speed	106 mph
0 - 100 km/h	13.0 seconds
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP	
Max. torque	140 Nm at 2.250 rpm	
Engine capacity	898 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	44.8 mpg	
Consumption extra urban	58.8 mpg	
Consumption combined	2.8 mpg	
CO2 emission	122 g/km	
CO2 label	D	



CarCheck.co.uk page 1/11



report date: 2024-03-28


# Internet history


## Entry 1

Date 2022-01-15

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



**MOT** history

MOT expiry date	2025-01-11
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #4		2024-01-09 16:12
MOT test	number	675532250214
Result		✓ Passed
Next expi	ry date	2025-01-11
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Advice</b> adjustmen	Parking Brake requirements only just met. It would appear that the braking s t or repair	system requires

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT** #3 2024-01-09 10:57 993527980594 **MOT** test number Result × Failed **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Parking Brake requirements only just met. It would appear that the braking system requires adjustment or repair Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail

MOT #2	2023-01-09 11:48
MOT test number	773830629436
Result	<b>✓</b> Passed
MOT #1	2022-01-12 13:01
MOT test number	195832926827
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	11 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Damage 2	
Date	
Category	
Туре	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history		
For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a> .		
*********		
***************************************		
***********		
**********		
************		
	More info >	
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates	,	
Current registration	NK NE	
Plate since		
Current registration	NK SIN	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-03-13
Last registration	2024-01-09
Complete history	See info



Registration #1	2019-03-13	26 mi
Registration #2	2022-01-12	26.126 mi
Registration #3		11,777 mi
Registration #4		71,777 es
Registration #5		71,777 66
Registration #6		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

The RENAULT factory car options list is only available in the premium report.		
S0225	Air conditioning	
S0295		
S0482		
S0501		
S0566		
S0567		

View the complete RENAULT factory list for this vehicle <u>here</u>.

More info >

## Safety ratings

**S0569** 

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1248 kg
Max. allowed weight	1659 kg

## Additional information

Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** D698154