



report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR
Colour	Black
Year of manufacture	2001
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	370 BHP
Max. torque	525 Nm at 3.600 rpm
Engine capacity	3.996 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.9 mpg
Consumption extra urban	29.3 mpg
Consumption combined	23.1 mpg
CO2 emission	301 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-05-28
Pictures	25
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	31
Total items failed	11

MOT #23	2024-02-15 13:08
MOT test number	106803939311
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #22**

2024-02-12 13:34

**MOT test number**

869168795551

**Result****✗ Failed**

**Advice** Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))

**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #21**

2023-03-01 14:18

**MOT test number**

139421851530

**Result****✓ Passed**

**MOT #20** 2023-02-10 11:24**MOT test number** 861200656585**Result** ✗ Failed

- Advice** Covers fitted
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear sill/floor area corroded
- Advice** Offside Front Brake pipe corroded, covered in grease or other material at floor corroded (1.1.11 (c))
- Advice** Rear high level brake light inop
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MOT #19** 2022-02-19 12:39**MOT test number** 301253506177**Result** ✓ Passed**MOT #18** 2021-01-08 09:30**MOT test number** 560668938814**Result** ✓ Passed**MOT #17** 2020-02-06 16:07**MOT test number** 867469485722**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #16</b>	2019-02-01 10:47
<b>MOT test number</b>	930809372254
<b>Result</b>	✓ Passed
<b>Advice</b>	Brake pad(s) wearing thin All (1.1.13 (a) (ii))

<b>MOT #15</b>	2019-01-29 12:57
<b>MOT test number</b>	490903876299
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Brake pad(s) wearing thin All (1.1.13 (a) (ii))

<b>MOT #14</b>	2018-01-24 09:45
<b>MOT test number</b>	694191357102
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Tyre worn close to the legal limit Both (4.1.E.1)
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Nearside Rear Body has slight corrosion Sill (6.1.B.2)
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)

<b>MOT #13</b>	2017-01-20 10:08
<b>MOT test number</b>	822160446135
<b>Result</b>	✓ Passed

**MOT #12** 2016-01-29 15:26**MOT test number** 778885210774**Result** ✓ Passed**Advice** Front brake discs scored worn and lipped**Advice** Rear brake pads wearing thin**Advice** Front brake pads wearing thin**Advice** Rear discs lipped**MOT #11** 2014-10-09 17:22**MOT test number** 845492184270**Result** ✓ Passed**Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**MOT #10** 2013-08-01 11:13**MOT test number** 567383213299**Result** ✓ Passed**MOT #9** 2013-07-31 11:24**MOT test number** 109962913244**Result** ✗ Failed**Fail** Offside Outer Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #8** 2012-08-02 11:01**MOT test number** 635575712276**Result** ✓ Passed**Notice** Oil leak**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Fuel pipe/s corroded**MOT #7** 2011-07-30 14:24**MOT test number** 368191211424**Result** ✓ Passed**MOT #6** 2010-07-23 14:34**MOT test number** 980044600209**Result** ✓ Passed**MOT #5** 2010-07-17 10:23**MOT test number** 102268890112**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2009-07-25 10:45**MOT test number** 734166509272**Result** ✓ Passed**MOT #3** 2008-04-24 09:58**MOT test number** 901185118189**Result** ✓ Passed





MOT #2	2007-04-16 16:44
MOT test number	700886707140
Result	✓ Passed

MOT #1	2006-07-25 11:18
MOT test number	114736606213
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2001-11-08
Last registration	2024-02-15
Complete history	<a href="#">See info</a>



Registration #1	2001-11-08	10 mi
Registration #2	2006-07-25	51.429 mi
Registration #3	2007-04-16	58.809 mi
Registration #4	2008-04-24	62.439 mi
Registration #5	2009-07-25	64.408 mi
Registration #6	2010-07-17	65.403 mi
Registration #7	2010-07-23	65.415 mi
Registration #8	2011-07-30	66.263 mi
Registration #9	2012-08-02	69.752 mi
Registration #10	2013-07-31	75.091 mi
Registration #11	2013-08-01	75.091 mi
Registration #12	2014-10-09	80.475 mi
Registration #13	2016-01-29	86.211 mi
Registration #14	2016-01-29	86.211 mi
Registration #15	2016-01-29	86.211 mi
Registration #16	2016-01-29	86.211 mi
Registration #17	2016-01-29	86.211 mi
Registration #18	2016-01-29	86.211 mi
Registration #19	2016-01-29	86.211 mi
Registration #20	2016-01-29	86.211 mi
Registration #21	2016-01-29	86.211 mi
Registration #22	2016-01-29	86.211 mi
Registration #23	2016-01-29	86.211 mi
Registration #24	2016-01-29	86.211 mi
Registration #25	2016-01-29	86.211 mi
Registration #26	2016-01-29	86.211 mi

**More info** >





Dimensions & weight

Width	2015 mm
Height	1296 mm
Length	4760 mm
Wheel base	2588 mm

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	PB0103251301