



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	Purple
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	57.7 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F






Internet history

Entry 2


Date	2023-11-05
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-05-17
Pictures	21
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-10-23
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	13
Total items failed	7

MOT #11	2023-10-14 09:08
MOT test number	107655831349
Result	✓ Passed
Next expiry date	2024-10-23
Advice	Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))
Advice	Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))

MOT #10	2022-10-14 13:04
MOT test number	709718833288
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9** 2022-10-14 10:35**MOT test number** 452933380517**Result** ✗ Failed**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2021-10-22 13:41**MOT test number** 994169559962**Result** ✓ Passed**MOT #7** 2020-10-12 10:39**MOT test number** 446356298328**Result** ✓ Passed**Advice** Rear Exhaust bracket broken..Exhaust still secure**MOT #6** 2020-10-12 10:39**MOT test number** 163991016277**Result** ✗ Failed**Advice** Rear Exhaust bracket broken..Exhaust still secure**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #5** 2019-10-14 10:40**MOT test number** 901190907523**Result** ✓ Passed

**MOT #4** 2019-10-14 08:51**MOT test number** 775962647100**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Exhaust system insecure Front bracket & rear bracket broken (6.1.2 (a))**MOT #3** 2018-10-10 15:37**MOT test number** 135623506780**Result** ✓ Passed**Advice** Nearside Rear tyre developing flat spots on inner edge**MOT #2** 2018-10-10 13:33**MOT test number** 192181497266**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick offside rear inner pad below limit (1.1.13 (a) (ii))**Advice** Nearside Rear tyre developing flat spots on inner edge**Fail** Offside Rear Exhaust system insecure exhaust hanger broken above rear beam (6.1.2 (a))**MOT #1** 2017-10-24 15:43**MOT test number** 316820187790**Result** ✓ Passed**Advice** Rear Exhaust bracket broken



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
23 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	23 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-30
Last registration	2023-10-14
Complete history	<a href="#">See info</a>



Registration #1	2014-12-30	26 mi
Registration #2	2017-10-24	18.716 mi
Registration #3	2018-10-10	33.390 mi
Registration #4	2018-10-10	33.392 mi
Registration #5	2019-10-14	44.063 mi
Registration #6	2019-10-14	44.063 mi
Registration #7	2020-10-12	53.434 mi
Registration #8	2020-10-12	53.434 mi
Registration #9	2020-10-12	53.434 mi
Registration #10	2020-10-12	53.434 mi
Registration #11	2020-10-12	53.434 mi
Registration #12	2020-10-12	53.434 mi
Registration #13	2020-10-12	53.434 mi
Registration #14	2020-10-12	53.434 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1145 kg
Max. allowed weight	1587 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCK2056302