





General information

| Make | MINI | |
|--------------------------|---------------------|--|
| Model | COUNTRYMAN COOPER D | |
| Black | | |
| Year of manufacture 2017 | | |
| Top speed132 mph | | |
| 0 - 60 mph | 8.6 seconds | |
| Gearbox | 6 speed Manual | |

Engine & fuel consumption

| Power | 150 BHP |
|-------------------------|---------------------|
| Max. torque | 330 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 113 g/km |
| CO2 label | С |







Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-02-02 |
| Pictures | 10 |
| Listing price | View report |









source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-07-01 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 1 |

| MOT #5 | 2023-06-21 16:09 |
|---------------------------------|------------------|
| MOT test number | 401942487517 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-01 |
| Advice Engine coolant level low | |

| MOT #4 | 2023-06-21 15:15 |
|--|------------------|
| MOT test number | 742102235169 |
| Result | 🗙 Failed |
| FailWindscreen wiper does not clear the windscreen effectively Both sides (3.4 (b) (ii))AdviceEngine coolant level low | |

| MOT #3 | 2022-06-17 09:00 |
|-----------------|------------------|
| MOT test number | 753323671267 |
| Result | ✓ Passed |

| MOT #2 | 2021-07-02 11:31 |
|---|------------------|
| MOT test number | 860330606271 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #1 | | 2020-11-16 16:02 |
|----------|--|------------------|
| MOT test | number | 889459010121 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|-------------------------|-------------------------|
| Tax due: 1 July 2024 | Expires: 1 July 2024 |
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 1 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2017-09-11 |
| Last registration | 2023-06-21 |
| Complete history | See info |



| Registration #1 | 2017-09-11 | 25 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-11-16 | 37.942 mi |
| Registration #3 | | 11.777 mi |
| Registration #4 | 2021-07-02 | 37.943 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.227 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| 50566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 68% |
| Pedestrian | 68% |
| Safety systems | 67% |
| Overall rating | 77% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2022 mm |
| Height | 1441 mm |
| Length | 4253 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1395 kg |
| Max. allowed weight | 1910 kg |
| Additional information | |
| Fuel tank capacity | 48 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |