



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Blue
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-07-16
Pictures	26
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-15
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-21
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	35
Total items failed	17

MOT #18	2023-01-02 14:09
MOT test number	927296628388
Result	✓ Passed
Next expiry date	2024-01-21
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17	2023-01-02 12:54
MOT test number	204346465219
Result	✗ Failed
Fail	Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm Both (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16	2022-01-03 12:37
MOT test number	877410594500
Result	✓ Passed



MOT #15	2021-01-22 12:09
MOT test number	378066674665
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #14	2019-12-31 09:05
MOT test number	281355215763
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2019-12-30 10:06
MOT test number	498551153867
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2019-01-18 15:22
MOT test number	718872022344
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2019-01-18 11:22

MOT test number

121789432588

Result

✗ Failed

- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn front trailing arm bush (5.3.4 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Registration plate inscription illegible (0.1 (b))
- Fail** Nearside Outer Position lamp not working (4.2.1 (a))

MOT #10

2018-01-10 11:59

MOT test number

328284377149

Result

✓ Passed

- Advice** Nearside Rear Trailing arm has slight play in a pin/bush front bush (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #9

2018-01-10 11:59

MOT test number

707019336545

Result

✗ Failed

- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear Trailing arm has slight play in a pin/bush front bush (2.4.G.2)

**MOT #8** 2017-01-16 09:19**MOT test number** 872712918470**Result** ✓ Passed**Advice** Both rear tyres wearing on inner edges**Advice** Offside front tyre slight outewr wall damage**MOT #7** 2017-01-16 09:19**MOT test number** 861194623765**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside front tyre slight outewr wall damage**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Both rear tyres wearing on inner edges**MOT #6** 2016-01-22 12:16**MOT test number** 515631276330**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside front tyre worn on inner and outer edges

**MOT #5** 2016-01-21 16:22**MOT test number** 411726497591**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside front tyre worn on inner and outer edges**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2014-05-07 14:15**MOT test number** 258157524441**Result** ✓ Passed**MOT #3** 2014-05-06 14:00**MOT test number** 265516124464**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2013-04-24 10:56**MOT test number** 955314913194**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #1	2012-05-02 14:48
MOT test number	519193122122
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✗
MOT

Expired:
21 January 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	21 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-05-19
Last registration	2023-01-02
Complete history	See info



Registration #1	2009-05-19	20 mi
Registration #2	2012-05-02	44.859 mi
Registration #3	2013-04-24	59.508 mi
Registration #4	2014-05-06	75.421 mi
Registration #5	2014-05-07	75.421 mi
Registration #6	2016-01-21	107.888 mi
Registration #7	2016-01-22	107.888 mi
Registration #8	2017-01-16	124.628 mi
Registration #9	2017-01-16	124.628 mi
Registration #10	2018-01-10	143.251 mi
Registration #11	2018-01-10	143.251 mi
Registration #12	2019-01-01	161.874 mi
Registration #13	2019-01-01	161.874 mi
Registration #14	2019-01-01	161.874 mi
Registration #15	2019-01-01	161.874 mi
Registration #16	2019-01-01	161.874 mi
Registration #17	2019-01-01	161.874 mi
Registration #18	2019-01-01	161.874 mi
Registration #19	2019-01-01	161.874 mi
Registration #20	2019-01-01	161.874 mi
Registration #21	2019-01-01	161.874 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K79192