



RENAULT

 **HNI4YFK**

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V EXTRA
Colour	White
Year of manufacture	2014
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 2

Date	2022-04-24
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-11
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	41
Total items failed	13

MOT #13	2024-02-12 10:20
MOT test number	414345501838
Result	✓ Passed
Next expiry date	2025-02-11

MOT #12	2024-01-30 10:46
MOT test number	891350924641
Result	✗ Failed
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
MAJOR	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11	2022-12-29 18:12
MOT test number	434142979711
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10** 2022-12-29 10:05**MOT test number** 202889402643**Result** ✗ Failed**MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Horn not working (7.7 (a))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Offside Rear Shock absorbers damaged to the extent that it does not function (5.3.2 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9** 2021-12-11 13:59**MOT test number** 305771804548**Result** ✓ Passed**Advice** Oil leak, but not excessive Power Steering (8.4.1 (a) (i))**MOT #8** 2021-12-11 13:59**MOT test number** 208093571029**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Oil leak, but not excessive Power Steering (8.4.1 (a) (i))**MOT #7** 2020-12-19 12:24**MOT test number** 649611994625**Result** ✓ Passed

**MOT #6**

2019-12-04 12:47

**MOT test number**

541008991289

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Chip in the windscreen

**MOT #5**

2019-12-04 12:47

**MOT test number**

912901033189

**Result**

✗ Failed

- Pass with rectification** Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Chip in the windscreen
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Fuel cap/sealing device ineffective (6.1.3 (b) (i))
- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4**

2018-08-10 09:09

**MOT test number**

955152875812

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))

**MOT #3** 2018-08-09 09:07**MOT test number** 875959071746**Result** ✗ Failed**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MAJOR** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #2** 2017-08-11 11:52**MOT test number** 267312039599**Result** ✓ Passed**Advice** Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement both (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Play in steering rack inner joint(s)



MOT #1	2017-08-07 16:34
MOT test number	471823354999
Result	✗ Failed
Fail	Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Play in steering rack inner joint(s)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Fail	Hazard warning switch faulty (1.4.B.1d)
Fail	Nearside Front Brake hose seriously damaged (found during steering lock to lock check) (2.2.D.2b)
Advice	Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement both (2.4.G.2)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Fuel cap/sealing device missing (7.2.4a)



Tax & MOT check

X

Untaxed

Tax expired:  
31 December 2023

✓

MOT

Expires:  
11 February 2025

Tax status	Expired at 31 December 2023
Days left	121 days too late
MOT expiry date	11 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>HN14YFK</b>
Plate since	2019-03-29
Current registration	<b>HN14YFK</b>
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-06-11
Last registration	2024-02-12
Complete history	<a href="#">See info</a>



Registration #1	2014-06-11	15 mi
Registration #2	2017-08-07	78.232 mi
Registration #3	2017-08-11	78.232 mi
Registration #4	2018-08-09	83.874 mi
Registration #5	2018-08-10	83.874 mi
Registration #6	2019-12-04	91.721 mi
Registration #7	2019-12-04	91.721 mi
Registration #8	2020-12-19	102.566 mi
Registration #9	2020-12-19	102.566 mi
Registration #10	2020-12-19	102.566 mi
Registration #11	2020-12-19	102.566 mi
Registration #12	2020-12-19	102.566 mi
Registration #13	2020-12-19	102.566 mi
Registration #14	2020-12-19	102.566 mi
Registration #15	2020-12-19	102.566 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5399 mm
Kerb weight	1710 kg
Max. allowed weight	2790 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C155405