



PEUGEOT



A06IHWR

report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Red
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-31
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	32
Total items failed	2

MOT #14 2023-10-30 14:47

MOT test number 445693884102

Result ✓ Passed

Next expiry date 2024-11-04

- Advice** Exhaust mounting defective rear mounting defective and rear one on back corroded almost away (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #13 2022-10-24 13:28

MOT test number 508975731128

Result ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coolant below minimum

**MOT #12**

2022-10-24 11:58

MOT test number

876277622355

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Coolant below minimum**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Items removed from driver's view prior to test**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11**

2021-11-05 07:36

MOT test number

999871006515

Result**✓ Passed****MOT #10**

2021-06-30 11:27

MOT test number

922155325020

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9**

2021-06-29 11:05

MOT test number

697836576155

Result**✗ Failed****MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #8	2020-11-09 12:27
MOT test number	914921354567
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2019-11-11 12:33
MOT test number	106612977652
Result	✓ Passed
Advice	Engine covers fitted and/or under trays fitted, not allowing full inspection
Advice	Nearside Front Tyre slightly damaged/cracking or perishing and nearside rear, cracking (5.2.3 (d) (ii))
Advice	Wheel trims fitted not allowing full inspection off wheel attachment bolts/nuts/tyre valves

MOT #6	2019-11-11 12:33
MOT test number	562002540532
Result	✗ Failed
Advice	Engine covers fitted and/or under trays fitted, not allowing full inspection
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Wheel trims fitted not allowing full inspection off wheel attachment bolts/nuts/tyre valves
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing and nearside rear, cracking (5.2.3 (d) (ii))

MOT #5	2018-10-23 11:03
MOT test number	477782881585
Result	✓ Passed
Advice	Exhaust front pipe mounting bracket badly corroded

**MOT #4** 2017-10-30 10:08**MOT test number** 542887296450**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #3** 2016-11-10 10:26**MOT test number** 320592395558**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust mounting in poor condition**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-11-02 15:34**MOT test number** 769764800052**Result** ✓ Passed**MOT #1** 2014-11-11 15:23**MOT test number** 358315414383**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
4 November 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-11
Last registration	2023-10-30
Complete history	See info



Registration #1	2011-11-11	6 mi
Registration #2	2014-11-11	16.160 mi
Registration #3	2015-11-02	19.683 mi
Registration #4	2016-11-10	25.104 mi
Registration #5	2017-10-30	34.958 mi
Registration #6	2018-10-23	41.669 mi
Registration #7	2019-11-11	54.528 mi
Registration #8	2019-11-11	54.528 mi
Registration #9	2019-11-11	54.528 mi
Registration #10	2019-11-11	54.528 mi
Registration #11	2019-11-11	54.528 mi
Registration #12	2019-11-11	54.528 mi
Registration #13	2019-11-11	54.528 mi
Registration #14	2019-11-11	54.528 mi
Registration #15	2019-11-11	54.528 mi
Registration #16	2019-11-11	54.528 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FSX46458693