



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 SE LUX NAV
Colour	White
Year of manufacture	2014
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 2

Date	2022-10-08
Pictures	26
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-08
Pictures	36
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-09
MOT pass rate	50 %
MOT passed	7
Failed MOT tests	7
Total advice items	4
Total items failed	13

MOT #14	2023-06-05 13:56
MOT test number	806866662587
Result	✓ Passed
Next expiry date	2024-06-09
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))
Minor	Stop lamp(s) with a multiple light source up to 1/2 not functioning high level (4.3.1 (a) (i))

MOT #13	2023-05-27 09:56
MOT test number	923126448320
Result	✗ Failed
Minor	Stop lamp(s) with a multiple light source up to 1/2 not functioning high level (4.3.1 (a) (i))
Fail	Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))

MOT #12	2022-06-01 11:44
MOT test number	501003975675
Result	✓ Passed

**MOT #11** 2022-06-01 11:37**MOT test number** 400126912083**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #10** 2021-06-10 11:18**MOT test number** 222108559880**Result** ✓ Passed**MOT #9** 2021-06-04 16:04**MOT test number** 799487346308**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #8** 2020-10-21 14:59**MOT test number** 797406706679**Result** ✓ Passed**MOT #7** 2020-10-21 13:21**MOT test number** 812367084847**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #6** 2020-10-20 10:42**MOT test number** 316997316807**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #5** 2019-11-12 16:38**MOT test number** 259795256309**Result** Passed**MOT #4** 2019-11-12 11:11**MOT test number** 834125969519**Result** Failed**Fail** Front Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))**Fail** Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))**Fail** Rear Brake disc significantly and obviously worn both (1.1.14 (a) (i))**MOT #3** 2018-11-09 09:25**MOT test number** 439271280745**Result** Passed**MOT #2** 2017-10-26 13:24**MOT test number** 326883968229**Result** Passed**MOT #1** 2017-10-25 13:09**MOT test number** 755829710488**Result** Failed**Fail** Offside Side repeater not working (1.4.A.2c)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LR64UDX
Plate since	2019-09-28
Current registration	LR64UDX
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2014-09-25
Last registration	2023-06-05
Complete history	See info



Registration #1	2014-09-25	21 mi
Registration #2	2017-10-25	48.268 mi
Registration #3	2017-10-26	48.268 mi
Registration #4	2018-11-09	57.767 mi
Registration #5	2019-11-12	70.378 mi
Registration #6	2019-11-12	70.383 mi
Registration #7	2020-10-20	77.339 mi
Registration #8	2020-10-21	77.349 mi
Registration #9	2020-10-21	77.350 mi
Registration #10	2020-10-21	77.350 mi
Registration #11	2020-10-21	77.350 mi
Registration #12	2020-10-21	77.350 mi
Registration #13	2020-10-21	77.350 mi
Registration #14	2020-10-21	77.350 mi
Registration #15	2020-10-21	77.350 mi
Registration #16	2020-10-21	77.350 mi
Registration #17	2020-10-21	77.350 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1764 kg
Max. allowed weight	2485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1104229