





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Purple
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-03

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-04
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #11		2023-06-19 10:26
MOT test	number	440809654550
Result		✓ Passed
Next expi	ry date	2024-07-04
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened by	poth front (1.1.14 (a)
Advice	Front Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #10		2022-06-09 09:18
MOT test i	number	243551548481
Result		✓ Passed
Advice	Offside Brake pipe corroded, covered in grease or other material front to r	rear (1.1.11 (c))

MOT #9		2021-07-05 15:36
MOT test	number	172849865149
Result		✓ Passed
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing Wall (5.2.3 (d)	(ii))
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing Wall (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2021-07-05 15:36

MOT test number 254759692412

Result X Failed

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing Wall (5.2.3 (d) (ii))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing Wall (5.2.3 (d) (ii))

Pass with rectification Offside Front Direction indicator not working (4.4.1 (a) (ii))

MOT #7 2020-06-16 15:47

MOT test number 794578968612

Result ✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #6 2020-06-16 09:43

MOT test number 876524773571

Result ★ Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt locking device missing (2.1.3 (g) (ii))

DANGEROUS Offside Front Suspension arm ball joint likely to become detached locking device missing (5.3.4 (a) (ii))

MAJOR Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2019-04-15 16:35
MOT test number	224978758196
Result	✓ Passed
MOT #4	2017-10-18 12:56
MOT test number	589875637222
Result	✓ Passed
MOT #3	2016-09-20 09:41
MOT test number	224646241160
Result	✓ Passed
MOT #2	2016-09-20 09:00
MOT test number	381325632296
Result	× Failed
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #1	2015-09-23 08:18
MOT test number	573821922379
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	hicton
Owner	HISTOIN

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-10-26
Last registration	2023-06-19
Complete history	See info



Registration #1	2012-10-26	20 mi
Registration #2	2015-09-23	16.968 mi
Registration #3	2016-09-20	23.175 mi
Registration #4	2016-09-20	23.175 mi
Registration #5	2017-10-18	25.902 mi
Registration #6	2020-06-16	38.167 mi
Registration #7		91.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	925 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	7232258

CarCheck.co.uk page 12/12