



SL08DLY

report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 30SWB 100 MULTIJET P/V
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-02-14
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	44
Total items failed	6

MOT #17	2023-02-15 12:54
---------	------------------

MOT test number	641883790338
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-02-14
------------------	------------

- Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced outrigger to inner sill (6.1.1 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated rubber cracking (5.3.4 (b) (i))
- Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced outrigger to inner sill (6.1.1 (c) (i))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced sill to arch holed (6.1.1 (c) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear exhaust tip heavily corroded
- Advice** Brake pipe corroded, covered in grease or other material all brake pipes (1.1.11 (c))
- Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #16**

2022-01-25 16:09

**MOT test number**

961990133445

**Result**

✓ Passed

**Advice** Both rear hand brake cables not moving much but brake readings have met the requirements. advise investigation & repair

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Nearside Front outer sill corroded and holed

**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #15**

2022-01-20 12:45

**MOT test number**

742377078034

**Result**

✗ Failed

**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Both rear hand brake cables not moving much but brake readings have met the requirements. advise investigation & repair

**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively damaged significantly reducing structural strength inner & outer sill holed & corroded (5.3.6 (a) (i))

**MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

**MAJOR** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Front outer sill corroded and holed

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MAJOR** Offside Rear Suspension component mounting prescribed area excessively damaged significantly reducing structural strength inner & outer sill holed & corroded (5.3.6 (a) (i))

**MOT #14**

2021-01-29 13:57

**MOT test number**

618324229748

**Result**

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside front outer sill corroded and holed
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material front to rear pipes covered in grease, unable to assess (1.1.11 (c))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Large amount of corrosion to front and rear suspension, not weakened.

**MOT #13**

2019-04-18 08:21

**MOT test number**

558818717930

**Result**

✓ Passed

**MOT #12**

2019-04-15 14:29

**MOT test number**

292355811778

**Result**

✗ Failed

- MAJOR** Nearside Rear Brake cable damaged (1.1.15 (a))
- MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Offside Rear Brake cable damaged (1.1.15 (a))

**MOT #11**

2018-04-04 15:26

**MOT test number**

582589970230

**Result**

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases box (7.1.2)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #10** 2017-04-25 10:49**MOT test number** 343547968252**Result** ✓ Passed**Advice** Nearside Headlamp damaged but light output not reduced (1.7.5a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2017-04-25 10:49**MOT test number** 561588085169**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Headlamp damaged but light output not reduced (1.7.5a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Macpherson strut insecure (2.4.G.1)**MOT #8** 2016-04-04 08:49**MOT test number** 544366748669**Result** ✓ Passed**MOT #7** 2015-04-07 16:44**MOT test number** 767727295057**Result** ✓ Passed**MOT #6** 2015-04-07 16:44**MOT test number** 519167195082**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)

**MOT #5** 2014-04-22 16:45**MOT test number** 207412414410**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-04-21 10:27**MOT test number** 935781314122**Result** ✗ Failed**Fail** Centre Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**MOT #3** 2013-04-09 11:06**MOT test number** 476179993005**Result** ✓ Passed**MOT #2** 2012-04-24 15:19**MOT test number** 938135112100**Result** ✓ Passed**MOT #1** 2011-03-25 14:07**MOT test number** 707934881061**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-31
Last registration	2023-02-15
Complete history	<a href="#">See info</a>



Registration #1	2008-03-31	27 mi
Registration #2	2011-03-25	35.895 mi
Registration #3	2012-04-24	45.054 mi
Registration #4	2013-04-09	51.383 mi
Registration #5	2014-04-21	58.181 mi
Registration #6	2014-04-22	58.181 mi
Registration #7	2015-04-07	64.717 mi
Registration #8	2016-04-04	70.344 mi
Registration #9	2017-04-25	75.928 mi
Registration #10	2018-04-25	81.512 mi
Registration #11	2019-04-25	87.096 mi
Registration #12	2020-04-25	92.680 mi
Registration #13	2021-04-25	98.264 mi
Registration #14	2022-04-25	103.848 mi
Registration #15	2023-02-15	109.432 mi
Registration #16	2023-02-15	109.432 mi
Registration #17	2023-02-15	109.432 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	0145163