



report date: 2024-03-28

General information

Make	BMW
Model	120 120D M SPORT
Colour	Blue
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-06
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-14
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	32
Total items failed	2

MOT #162023-06-15 15:02

MOT test number441575959375

Result✓ Passed

Next expiry date2024-06-14

- AdviceFront Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceNearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- AdviceNearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- AdviceRear Registration plate insecure but not likely to fall off (0.1 (a))
- AdviceOffside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- AdviceOffside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- AdviceRear Exhaust mounting defective (6.1.2 (a))



## MOT #15

2023-06-15 15:02

MOT test number

546387471708

## Result

✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

## MOT #14

2022-02-14 10:58

MOT test number

557531811190

## Result

✓ Passed

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

## MOT #13

2021-02-01 12:05

MOT test number

402999123821

## Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #12** 2020-02-03 11:02**MOT test number** 918008058960**Result** ✓ Passed**MOT #11** 2019-01-29 11:06**MOT test number** 873713453021**Result** ✓ Passed**MOT #10** 2018-02-09 17:56**MOT test number** 900060715675**Result** ✓ Passed**MOT #9** 2017-01-19 13:36**MOT test number** 841559864822**Result** ✓ Passed**Advice** Rear tyres wearing on inner edges**Advice** Front tyres wearing on outer edges**MOT #8** 2016-01-19 09:34**MOT test number** 715355385604**Result** ✓ Passed**Advice** Brake pad(s) wearing thin fronts 70% worn (3.5.1g)**MOT #7** 2015-01-21 10:32**MOT test number** 357111525084**Result** ✓ Passed**Notice** Offside front tyre slight wear on outter edge**Notice** Nearside front tyre slight wear on outter edge

**MOT #6** 2015-01-20 09:47**MOT test number** 125320425020**Result** ✗ Failed**Notice** Offside front tyre slight wear on outter edge**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nearside front tyre slight wear on outter edge**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-01-27 09:04**MOT test number** 827297324082**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-01-03 08:54**MOT test number** 316003103032**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2012-01-25 09:29**MOT test number** 469375822051**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/front and rear tyres on 3mm**MOT #2** 2011-01-07 10:05**MOT test number** 389347201083**Result** ✓ Passed



MOT #1	2010-01-28 11:19
MOT test number	173418620095
Result	✓ Passed
<div>Notice</div> Nail in nearside rear tyre	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
14 June 2024

Tax status		Valid until 1 July
Days left		64
MOT expiry date		14 June 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	<b>WU56ZDC</b>
Plate since	2019-03-28
Current registration	<b>WU56ZDC</b>
Plate since	2019-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-02-01
Last registration	2023-06-15
Complete history	<a href="#">See info</a>



Registration #1	2007-02-01	8 mi
Registration #2	2010-01-28	15.703 mi
Registration #3	2011-01-07	20.116 mi
Registration #4	2012-01-25	25.254 mi
Registration #5	2013-01-03	27.624 mi
Registration #6	2014-01-27	37.230 mi
Registration #7	2015-01-20	47.447 mi
Registration #8	2015-01-21	47.447 mi
Registration #9	2016-01-19	54.970 mi
Registration #10	2016-01-19	54.970 mi
Registration #11	2016-01-19	54.970 mi
Registration #12	2016-01-19	54.970 mi
Registration #13	2016-01-19	54.970 mi
Registration #14	2016-01-19	54.970 mi
Registration #15	2016-01-19	54.970 mi
Registration #16	2016-01-19	54.970 mi
Registration #17	2016-01-19	54.970 mi
Registration #18	2016-01-19	54.970 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1751 mm
Height	1430 mm
Length	4227 mm
Wheel base	2660 mm
Kerb weight	1340 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	84886445