



DA65GSV

report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H EXECUTIVE EDITION
Colour	Black
Year of manufacture	2015
Top speed	125 mph
0 - 60 mph	8.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





## MOT history

MOT expiry date	2024-11-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #6	2023-11-23 10:17
MOT test number	785985858391
Result	✓ Passed
Next expiry date	2024-11-22
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2022-08-02 12:21
MOT test number	136949755698
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4	2022-08-02 12:21
MOT test number	100353544548
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #3</b>	2021-08-24 12:19
---------------	------------------

<b>MOT test number</b>	366938391710
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	--

<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt
---------------	--

<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

<b>MOT #2</b>	2020-05-26 16:01
---------------	------------------

<b>MOT test number</b>	348561828834
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2019-05-10 09:22
---------------	------------------

<b>MOT test number</b>	792545875815
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
22 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	22 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 10,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 10,50,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2015-09-16
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2015-09-16	18 mi
Registration #2	2019-05-10	38.089 mi
Registration #3	2020-05-26	53.588 mi
Registration #4	2021-08-24	59.758 mi
Registration #5	2023-11-23	59.758 mi
Registration #6	2023-11-23	59.758 mi
Registration #7	2023-11-23	59.758 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AR1249887