





report date: 2024-03-29

General information

Make	CITROEN	
Model	C4 GRAND PICASSO BLUEHDI FEEL S/S EAT6	
Colour	Blue	
Year of manufacture	2017	
Top speed	117 mph	
0 - 60 mph	11.2 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-25

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-05-17
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	9
Total items failed	5

MOT #7		2024 04 22 15.14
MOT #7		2024-04-23 15:14
MOT test	number	546284707128
Result		✓ Passed
Next expiry date 2025-05-17		
Advice Nearside Front Tyre slightly damaged/cracking or perishing perished badly (5.2.3 (d) (ii))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii	i))

MOT #6	2024-04-23 08:45
MOT test number	935970998333
Result	× Failed
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing perished bad	ly (5.2.3 (d) (ii))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



Result

EA67CCV

report date: 2024-03-29

× Failed

 MOT #5
 2023-05-09 14:51

 MOT test number
 336846987228

 Result
 ✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2023-05-09 10:38

MOT test number 643620950450

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #3 2022-05-18 09:34

MOT test number 142184735634

Result ✓ Passed

MOT #2 2022-01-05 15:23

MOT test number 453602295479

Result X Failed

Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #1 2020-10-29 13:00

MOT test number 140887182320

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	17 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	hictory
Owner	TIISLUTY

e union matery		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		N
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		

	More info >	
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	OK SIE	
Plate since		
Current registration	UK ZIZ	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



EA67CCV report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



EA67CCV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-10-30
Last registration	2024-04-23
Complete history	See info



Registration #1	2017-10-30	10 mi
Registration #2	2020-10-29	8.324 mi
Registration #3		11.777 es
Registration #4	2022-01-05	9.073 mi
Registration #5	2022-05-18	9.073 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



EA67CCV report date: 2024-03-29

Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHD3066007

CarCheck.co.uk page 11/11