



report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER TD XS STATION WAGON
Colour	Black
Year of manufacture	2013
Top speed	90 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	30.1 mpg
Consumption combined	27.7 mpg
CO2 emission	269 g/km
CO2 label	M






Internet history

Entry 1

Date	2022-01-13
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-01-17
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #112024-01-18 14:14

MOT test number791145211663

Result✓ Passed

Next expiry date2025-01-17

- Advice

Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Minor

Steering box leaking oil (2.1.1 (e) (i))
- Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Oil leak, but not excessive transfer box (8.4.1 (a) (i))
- Advice

Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice

Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

**MOT #10**

2024-01-18 13:22

MOT test number

310131355802

Result**✗ Failed**

- Advice** Oil leak, but not excessive transfer box (8.4.1 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Nearside Rear Rear reflector missing (4.8.2 (a) (ii))
- Minor** Steering box leaking oil (2.1.1 (e) (i))
- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Rear Rear reflector missing (4.8.2 (a) (ii))

MOT #9

2023-01-12 12:15

MOT test number

818099853027

Result**✓ Passed****MOT #8**

2022-01-18 10:44

MOT test number

487457538319

Result**✓ Passed****MOT #7**

2021-12-10 15:48

MOT test number

644499485731

Result**✗ Failed**

- Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))



MOT #6	2020-12-17 09:07
--------	------------------

MOT test number	488152084103
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2019-01-26 11:30
--------	------------------

MOT test number	799577454863
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #4	2017-12-15 12:19
--------	------------------

MOT test number	355475589502
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #3	2017-01-28 10:37
--------	------------------

MOT test number	752691860732
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2017-01-28 10:37
--------	------------------

MOT test number	838876535067
-----------------	--------------

Result	✗ Failed
--------	----------

Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)
-------------------------	---

MOT #1	2016-01-11 16:14
--------	------------------

MOT test number	849686497490
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-30
Last registration	2024-01-18
Complete history	See info



Registration #1	2013-10-30	19 mi
Registration #2	2016-01-11	2.514 mi
Registration #3	2017-01-28	6.922 mi
Registration #4	2017-01-28	6.922 mi
Registration #5	2017-12-15	13.235 mi
Registration #6	2019-01-26	17.677 mi
Registration #7	2020-12-17	17.881 mi
Registration #8	2020-01-20	20.277 mi
Registration #9	2020-01-20	20.277 mi
Registration #10	2020-01-20	20.277 mi
Registration #11	2020-01-20	20.277 mi
Registration #12	2020-01-20	20.277 mi
Registration #13	2020-01-20	20.277 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	3880 mm
Wheel base	2360 mm
Kerb weight	1875 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	121026083529DT224