





report date: 2024-03-28

#### General information

| Make                | PEUGEOT        |
|---------------------|----------------|
| Model               | 207 SPORTIUM   |
| Colour              | Silver         |
| Year of manufacture | 2012           |
| Top speed           | 115 mph        |
| 0 - 60 mph          | 12.1 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 95 BHP              |
|-------------------------|---------------------|
| Max. torque             | 136 Nm at 4.000 rpm |
| Engine capacity         | 1.397 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 37.2 mpg            |
| Consumption extra urban | 58.9 mpg            |
| Consumption combined    | 48.7 mpg            |
| CO2 emission            | 135 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/14



report date: 2024-03-28

### Internet history

#### Entry 2

Date 2021-09-15

Pictures 24

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

| Date     | 2021-09-14 |
|----------|------------|
| Pictures | 24         |

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



SA12WHW
report date: 2024-03-28

MOT history

| MOT expiry date    | 2024-08-19 |
|--------------------|------------|
| MOT pass rate      | 77 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 3          |
| Total advice items | 29         |
| Total items failed | 14         |

| MOT #13  | 2023-07-27 10:24            |
|--|-----------------------------|
| MOT test number  | 116531992036                |
| Result   | ✓ Passed                    |
| Next expiry date   | 2024-08-19                  |
| Minor (b) (i))  Nearside Registration plate lamp inoperative in the case of multiple la                                  | mps or light sources (4.7.1 |
| Advice Rear Brakes imbalanced requirements only just met. It would appear requires adjustment or repair. (1.2.1 (b) (i)) | that the braking system     |
| Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))  |                             |
| Advice Rear axle and coil springs corroded   |                             |

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #12** 2023-07-25 14:33

**MOT test number** 501951401095

Result X Failed

Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Rear axle and coil springs corroded

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #11** 2022-08-16 14:38

MOT test number 922974811618

**Advice** Coolant leak lower radiator hose clip

Advice Offside Rear Tyre worn close to legal limit/worn on edge on 3mm and worn on outside edge (5.2.3 (e))

**Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #10** 2022-08-16 12:05

**MOT test number** 764097150425

**Result** X Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Offside Front Brake hose slightly twisted (1.1.12 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge on 3mm and worn on outside edge (5.2.3 (e))

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

**Advice** Coolant leak lower radiator hose clip

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #9 2021-08-20 09:48

**MOT test number** 635704090220

CarCheck.co.uk page 5/14



Pass with rectification

**SA12WHW** 

report date: 2024-03-28

**MOT #8** 2020-12-01 11:48 736206644268 **MOT** test number Result ✓ Passed **Advice** Both rear coil springs corroded **Advice** Front Exhaust mounting defective cracked and slightly blowing (6.1.2 (a)) Advice Offside Front Inner Tyre worn close to legal limit/worn on edge and outer 185/65/15hr (5.2.3 (e)) Advice Heavy corrosion front subframe and rear suspension beam Nearside Front Inner Tyre worn close to legal limit/worn on edge and outer 185/65/15hr (5.2.3 (e)) Advice Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning few led bulbs out (4.2.1 (a) (i)) **Advice** O/s/f suspension arm bushes peeling

| MOT #7          | 2019-06-17 10:33 |
|-----------------|------------------|
| MOT test number | 479692705719     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #6          | 2019-06-17 10:33 |
| MOT test number | 831610535745     |
| Result          | <b>×</b> Failed  |
|                 |                  |

Front Headlamp aim too high (4.1.2 (a))

| MOI #5                                  | 2018-00-13 14:52 |
|---|------------------|
| MOT test number                         | 924918234671     |
| Result                                  | <b>✓</b> Passed  |
|   |                  |
| MOT #4                                  | 2017-06-07 15:36 |
| MOT test number                         | 264356229687     |
| Result                                  | ✓ Passed         |
| Advice Nail in nearside rear tyre tread |                  |

CarCheck.co.uk page 6/14



report date: 2024-03-28

| MOT #3 | 2016-06-23 10:01 |
|--------|------------------|
|        |                  |

**MOT test number** 187536339946

MOT #2 2016-06-22 07:20

**MOT test number** 476386124544

Result 

Passed

MOT #1 2015-05-28 11:59

**MOT test number** 529118145154

**Result** ✓ Passed

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Exhaust hanger missing but system still suported

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



report date: 2024-03-28

#### Tax & MOT check





Expires: 19 August 2024

| Tax status       | Expired at 30 March 2024 |
|------------------|--------------------------|
| Days left        | 29 days too late         |
| MOT expiry date  | 19 August 2024           |
| Full MOT history | See MOT history          |

#### Tax calculation

| William .                               | 40         |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

| Owner | history |
|-------|---------|
|-------|---------|

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. |             |
|--|-------------|
|  |             |
|  |             |
|  |             |
| ***************************************  |             |
| ********   |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this PEUGEOT had different number plates.   |             |
| Number of plates   | ,           |
| Current registration   | AK<br>SIE   |
| Flate since  |             |
| Current registration   | NK SIE      |
| Flate since  |             |
|  | More info > |
|  |             |

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Registration #16

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 16         |
| First mileage registration | 2012-05-29 |
| Last registration          | 2023-07-27 |
| Complete history           | See info   |



| Registration #1  | 2012-05-29 | 24 mi     |
|------------------|------------|-----------|
| Registration #2  | 2015-05-28 | 33.932 mi |
| Registration #3  | 2016-06-22 | 42.697 mi |
| Registration #4  | 2016-06-23 | 42.707 mi |
| Registration #5  | 2017-06-07 | 49.843 mi |
| Registration #6  | 2018-06-13 | 57.263 mi |
| Registration #7  | 2019-06-17 | 68.698 mi |
| Registration #8  | 2019-06-17 | 68.698 mi |
| Registration #9  |            | 11.177 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.117 es |
| Registration #12 |            | 11.177 es |
| Registration #13 |            | 11.177 es |
| Registration #14 |            | 0.00 44   |
| Registration #15 |            | 11.777 mi |
|                  |            |           |

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1920 mm |
|---------------------|---------|
| Height              | 1502 mm |
| Length              | 4030 mm |
| Wheel base          | 2540 mm |
| Kerb weight         | 1219 kg |
| Max. allowed weight | 1626 kg |

# Additional information

| Fuel tank capacity                | 50 l                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 3                     |
| Number of seats<br>CarCheck.co.uk | 5 page 14/14          |

Number of axles 2

**Engine number** FGAS1441366