





report date: 2024-03-28

General information

Make	TOYOTA
Model	YARIS VVT-I ICON TECH
Colour	Red
Year of manufacture	2017
Top speed	109 mph
Gearbox	6 speed CVT

Engine & fuel consumption

Power	110 BHP
Max. torque	136 Nm at 4.400 rpm
Engine capacity	1.496 сс
Cylinders	4
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

_	_	_		_	-
드	n	C	ľν	7	1

ciitiy 1	
Date	2021-02-05
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/11



WD17HRO

report date: 2024-03-28

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2024-06-13
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #6	2023-06-14 09:23
MOT test number	458009933575
Result	✓ Passed
Next expiry date	2024-06-13

MOT #5	2022-08-25 08:49
MOT test number	188311408994
Result	✓ Passed

MOT #4	2021-09-09 13:54
MOT test number	137531230076
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2021-09-09 13:54	
MOT test number	563435923457	
Result	★ Failed	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))	

CarCheck.co.uk page 3/11



WD17HRO

report date: 2024-03-28

2020-10-20 10:10 **MOT #2** 716217776044 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Light cracking (5.2.3 (d) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge Outer shoulder bald (5.2.3 (e)) Advice Offside Front Tyre slightly damaged/cracking or perishing Light cracking (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing Light cracking (5.2.3 (d) (ii)) Nearside Front Tyre worn close to legal limit/worn on edge Outer shoulder Bald (5.2.3 (e)) **Advice** Advice Nearside Front Tyre slightly damaged/cracking or perishing Light cracking (5.2.3 (d) (ii))

MOT #1	2020-06-23 12:34
MOT test number	399935779874
Result	✓ Passed
Advice COVID-19 6 MONTH EXTENSION	

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

·	
Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-
Standard rate (12 months) Standard rate (6 months) Premium rate (12 months)	£ 180,00,- £ 99,00,- £ 570,00,-

CarCheck.co.uk page 5/11



WD17HRO

report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

ober of plates

WD17HRO

report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this TOYOTA had different number plates.

UK UK

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-06-30
Last registration	2023-06-14
Complete history	See info



Registration #1	2017-06-30	19 mi
Registration #2	2020-10-20	20.065 mi
Registration #3		11.777 es
Registration #4	2021-09-09	24.990 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioni
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	81%
Pedestrian	60%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3945 mm
Wheel base	2510 mm
Kerb weight	1065 kg
Max. allowed weight	1545 kg

Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/13

Number of axles 2

Engine number 2NR7022571