



AK05ZWG

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg





Internet history

Entry 1	
Date	2021-06-24
Pictures	15
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #22	2021-06-08 13:46
MOT test number	127777821952
Result	✓ Passed
Next expiry date	2022-06-17

MOT #21	2021-06-02 15:32
MOT test number	507093377092
Result	✗ Failed

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Windscreen wiper missing (3.4 (a))

MOT #20	2020-06-18 16:23
MOT test number	854922289010
Result	✓ Passed

Advice Offside Rear Handbrake Lever Not Returning to stop.

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Axle Corroded

**MOT #19**

2020-06-18 07:07

MOT test number

477523185372

Result**✗ Failed**

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Handbrake Lever Not Returning to stop.
- Fail** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Emissions not tested (8.2.1.2 (d))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Axle Corroded

MOT #18

2019-06-13 08:43

MOT test number

131186892171

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #17**

2018-06-18 11:09

MOT test number

179687190037

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material n/s front to rear (1.1.11 (c))
- Advice** O/s/r handbrake lever not fully returning
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #16

2018-06-18 11:09

MOT test number

902190216789

Result

✗ Failed

- Advice** Brake pipe corroded, covered in grease or other material n/s front to rear (1.1.11 (c))
- Advice** O/s/r handbrake lever not fully returning
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15

2017-06-15 11:56

MOT test number

415231235714

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)

**MOT #14**

2017-06-15 08:40

MOT test number

210961649093

Result**✗ Failed****Advice** Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Lower Direction indicator not working (1.4.A.2c)**Fail** Nearside Rear Inner Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13**

2016-06-14 13:18

MOT test number

952871538101

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #12**

2016-06-14 09:04

MOT test number

394057698649

Result**✗ Failed****Fail** Offside Rear rear brake binding (3.7.B.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #11** 2015-06-18 11:54**MOT test number** 646579765175**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)

MOT #10 2014-06-19 10:13**MOT test number** 585470474132**Result** ✓ Passed**MOT #9** 2013-05-04 13:03**MOT test number** 408544823170**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Center and rear exhaust mounts corroded

MOT #8 2013-05-04 09:46**MOT test number** 235124323445**Result** ✗ Failed

- Notice** Engine undertray fitted and slightly insecure
- Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Notice** Center and rear exhaust mounts corroded
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #7** 2012-05-05 16:45**MOT test number** 919146522142**Result** ✓ Passed

- Notice** Exhaust system corroded
- Notice** Nearside front wheel trim missing
- Notice** Rear exhaust mount corroded
- Notice** Slight brake bind both rear brakes
- Notice** Water inside offside rear light unit
- Notice** Center exhaust mount broken

MOT #6 2012-05-05 09:31**MOT test number** 936326422191**Result** ✗ Failed

- Notice** Water inside offside rear light unit
- Notice** Center exhaust mount broken
- Notice** Exhaust system corroded
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Notice** Nearside front wheel trim missing
- Notice** Rear exhaust mount corroded
- Notice** Slight brake bind both rear brakes
- Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #5 2011-05-14 10:13**MOT test number** 847844631122**Result** ✓ Passed

**MOT #4** 2011-05-14 10:13**MOT test number** 449954031140**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #3** 2010-05-15 09:50**MOT test number** 954585630162**Result** ✓ Passed**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2009-05-07 09:25**MOT test number** 580697429134**Result** ✓ Passed**MOT #1** 2008-05-02 09:22**MOT test number** 572283028113**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nail in nearside rear tyre**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-28
Current registration	 XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-15
Last registration	2021-06-08
Complete history	See info



Registration #1	2005-05-15	24 mi
Registration #2	2008-05-02	32.691 mi
Registration #3	2009-05-07	37.485 mi
Registration #4	2010-05-15	43.673 mi
Registration #5	2011-05-14	48.593 mi
Registration #6	2012-05-05	53.122 mi
Registration #7	2012-05-05	53.122 mi
Registration #8	2013-05-04	55.381 mi
Registration #9	2013-05-04	55.381 mi
Registration #10	2014-06-19	57.516 mi
Registration #11	2015-06-18	71.264 mi
Registration #12	2016-06-14	78.067 mi
Registration #13	2016-06-14	78.067 mi
Registration #14	2016-06-14	78.067 mi
Registration #15	2016-06-14	78.067 mi
Registration #16	2016-06-14	78.067 mi
Registration #17	2016-06-14	78.067 mi
Registration #18	2016-06-14	78.067 mi
Registration #19	2016-06-14	78.067 mi
Registration #20	2016-06-14	78.067 mi
Registration #21	2016-06-14	78.067 mi
Registration #22	2016-06-14	78.067 mi
Registration #23	2016-06-14	78.067 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1385 kg
Max. allowed weight	1757 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 036435