





report date: 2024-03-28

### General information

| Make                | MINI                |
|---------------------|---------------------|
| Model               | COOPER COOPER SPORT |
| Colour              | White               |
| Year of manufacture | 2019                |
| Top speed           | 127 mph             |
| Gearbox             | 7 speed automatic   |

# Engine & fuel consumption

| Power                | 134 BHP             |
|----------------------|---------------------|
| Max. torque          | 220 Nm at 4.200 rpm |
| Engine capacity      | 1.499 сс            |
| Cylinders            | 3                   |
| Fuel type            | Petrol              |
| Consumption combined | 44.1 mpg            |
| CO2 emission         | 125 g/km            |
| CO2 label            | D                   |



CarCheck.co.uk page 1/10



## Internet history

| <b>Entry</b> | 1 |
|--------------|---|
| y            | - |

| Liitiy 1      |             |
|---------------|-------------|
| Date          | 2022-07-06  |
| Pictures      | 0           |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/10



### **MOT** history

(5.2.3 (e))

| MOT expiry date    | 2024-08-26 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 3          |
| Total items failed | 0          |

| MOT #3           | 2023-08-17 11:22 |
|------------------|------------------|
| MOT test number  | 574030416136     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-08-26       |

| MOT #2          | 2022-08-27 10:43 |
|-----------------|------------------|
| MOT test number | 783608937931     |
| Result          | ✓ Passed         |

| MOT #1 | 2022-04-14 10:10 |
|--------|------------------|
|--------|------------------|

**MOT test number** 400868402347

Result ✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tyre 2-2.5mm worn to near bold on inner edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre2-2.7mm worn lower on outer edge

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre 2.5-3.5mm worn lower on inner edge

(5.2.3 (e))

CarCheck.co.uk page 3/10



# Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 95                   |
| MOT expiry date  | 26 August 2024       |
| Full MOT history | See MOT history      |

### Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | G          |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |
|                               |            |

CarCheck.co.uk page 4/10



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



## Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners di<br>Check it in the premium report and see all owner registrations. Download the full report  |           | e? |
|--|-----------|----|
|  |           |    |
| manage of the same |           |    |
| ***************************************  |           |    |
| ***************************************  |           |    |
| ********   |           |    |
|  |           |    |
| ***************************************  |           |    |
|  | More info | >  |
| Plate changes  |           |    |
| See in this check if this MINI had different number plates.  |           |    |
| Number of plates   |           |    |
| Current registration   | UK UK     |    |
| Plate since  |           |    |
| Current registration   | UK UK     |    |
| Plate since  |           |    |
|  | More info | >  |

CarCheck.co.uk page 7/10



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 8/10



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2019-04-15 |
| Last registration          | 2023-08-17 |
| Complete history           | See info   |



| Registration #1 | 2019-04-15 | 8 mi      |
|-----------------|------------|-----------|
| Registration #2 | 2022-04-14 | 32.566 mi |
| Registration #3 |            | 11.177 es |
| Registration #4 |            | 77,777 66 |
| Registration #5 |            | 11.777 es |

More info >

CarCheck.co.uk page 9/10




### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 73%             |
| Pedestrian     | 66%             |
| Safety systems | 56%             |
| Overall rating | 71%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1727 mm |
|---------------------|---------|
| Height              | 1415 mm |
| Length              | 3845 mm |
| Max. allowed weight | 1695 kg |

## Additional information

| Number of seats | 4        |
|-----------------|----------|
| Number of axles | 2        |
| Engine number   | 34575693 |

CarCheck.co.uk page 10/10