



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-12-23
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-22
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-06
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #12	2023-12-12 14:25
MOT test number	431017736572
Result	✓ Passed
Next expiry date	2025-01-06

MOT #11	2023-01-06 12:55
MOT test number	447686041776
Result	✓ Passed

MOT #10	2023-01-04 14:15
MOT test number	936273404895
Result	✗ Failed

MAJOR Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9	2022-01-07 14:11
MOT test number	436201083850
Result	✓ Passed

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Inner Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

**MOT #8** 2021-12-22 15:14**MOT test number** 790010085594**Result** ✗ Failed**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Nearside Front Inner Suspension arm pin or bush excessively worn marked red (5.3.4 (a) (i))**Advice** Nearside Front Inner Drive shaft joint worn, but not excessively (6.1.7 (c) (i))**MOT #7** 2020-12-11 10:53**MOT test number** 499593970560**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Under-tray and engine cover fitted**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2019-06-26 09:33**MOT test number** 301204886741**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2018-06-26 08:45**MOT test number** 937720329910**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2017-06-30 08:41**MOT test number** 965654084342**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2016-07-02 10:43**MOT test number** 724800833285**Result** ✓ Passed**MOT #2** 2015-07-01 10:53**MOT test number** 437112985105**Result** ✓ Passed**Notice** Offside front tyre worn inner edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2014-07-01 16:42**MOT test number** 346212384146**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
6 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	6 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-26
Last registration	2023-12-12
Complete history	See info



Registration #1	2011-03-26	8 mi
Registration #2	2014-07-01	23.077 mi
Registration #3	2015-07-01	30.935 mi
Registration #4	2016-07-02	35.157 mi
Registration #5	2017-06-30	39.439 mi
Registration #6	2018-06-26	46.548 mi
Registration #7	2019-06-26	56.207 mi
Registration #8	2020-12-11	71.774 mi
Registration #9	2021-06-30	81.277 mi
Registration #10	2022-06-30	91.277 mi
Registration #11	2023-06-30	101.277 mi
Registration #12	2023-12-12	111.277 mi
Registration #13	2024-03-29	121.277 mi
Registration #14	2024-03-29	131.277 mi
Registration #15	2024-03-29	141.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212